



Mercedes-Benz

SFI4LCE

report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	SPRINTER 519 CDI C/C
Colour	White
Year of manufacture	2014
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	440 Nm at 1.400 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-24
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-04-04
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	19
Total items failed	19

MOT #11	2022-04-05 08:57
MOT test number	273916828224
Result	✓ Passed
Next expiry date	2023-04-04
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #10	2022-04-04 12:35
MOT test number	936121292957
Result	✗ Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Prop shaft securing bolt missing (6.1.7 (a) (i))
Fail	Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #9	2020-04-14 10:31
MOT test number	876202758322
Result	✓ Passed



MOT #8	2019-04-24 10:45
MOT test number	497746309304
Result	✓ Passed
Minor	Offside Direction indicator flashing more than 120 times a minute (4.4.4 (a))
Advice	Offside Play in steering rack inner joint(s)

MOT #7	2019-04-19 13:30
MOT test number	753720590710
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Rear Position lamp not working sidelight inop (4.2.1 (a))
Fail	Steering wheel has excessive movement up and down (2.2.2 (a))
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Nearside Rear Suspension bellows damaged or deteriorated and function affected airbag through to cord (5.3.5 (b) (i))
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6	2018-04-24 10:57
MOT test number	871008443100
Result	✓ Passed

MOT #5	2017-03-31 20:02
MOT test number	892224701692
Result	✓ Passed
Advice	Offside Rear Inner Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Advice	Nearside Rear Inner Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #4**

2017-03-30 16:29

MOT test number

239267894329

Result**✗ Failed**

- Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Rear Inner Anti-roll bar attachment bracket/mounting insecure (2.4.G.1)
- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Rear Inner Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Fail** Nearside Front Headlamp aim too low (1.8)
- Fail** Nearside Rear Panhard rod has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Front Brake hose twisted (3.6.B.4c)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Rear Inner Anti-roll bar has slight play in a pin/bush (2.4.G.2)

MOT #3

2016-04-29 14:07

MOT test number

243229986759

Result**✓ Passed**

- Advice** Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nail in nearside rear outer tyre tread
- Advice** Engine management light on
- Advice** Offside Rear Outer Tyre worn close to the legal limit (4.1.E.1)



MOT #2

2016-04-28 10:18

MOT test number

755174742804

Result		✗ Failed
Advice	Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nail in nearside rear outer tyre tread	
Fail	Offside Rear Inner Anti-roll bar has excessive play in a pin/bush (2.4.G.2)	
Fail	Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)	
Advice	Engine management light on	
Advice	Offside Rear Outer Tyre worn close to the legal limit (4.1.E.1)	
Fail	Nearside Rear Inner Anti-roll bar has excessive play in a pin/bush (2.4.G.2)	
Fail	Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)	

MOT #1

2015-04-28 14:24

MOT test number

345178515117

Result

✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 April 2023

✕
MOT

Expired:
4 April 2023

Tax status

Expired at 1 April 2023

Days left

395 days too late

MOT expiry date

4 April 2023

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-04-29
Last registration	2022-04-05
Complete history	See info



Registration #1	2014-04-29	17 mi
Registration #2	2015-04-28	47.430 mi
Registration #3	2016-04-28	101.008 mi
Registration #4	2016-04-29	101.015 mi
Registration #5	2017-03-30	146.630 mi
Registration #6	2017-03-31	146.630 mi
Registration #7	2018-04-24	192.819 mi
Registration #8	2019-04-29	241.277 mi
Registration #9	2020-04-29	291.277 mi
Registration #10	2021-04-29	341.277 mi
Registration #11	2022-04-29	391.277 mi
Registration #12	2023-04-29	441.277 mi
Registration #13	2024-04-29	491.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Engine number	64289641408310