



WN6IUUT

report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	Black
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-12
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	31
Total items failed	6

MOT #14	2023-08-30 10:58
MOT test number	793406914382
Result	✓ Passed
Next expiry date	2024-09-19

MOT #13	2022-09-06 10:27
MOT test number	304074084905
Result	✓ Passed

MOT #12	2022-09-06 10:27
MOT test number	173110191835
Result	✗ Failed
<div>Pass with rectification</div> Front Position lamp not working o/s-n/s (4.2.1 (a) (ii))	

MOT #11	2021-09-20 13:05
MOT test number	583052785742
Result	✓ Passed

MOT #10	2020-07-06 14:46
MOT test number	741059372622
Result	✓ Passed

**MOT #9** 2020-07-03 09:38**MOT test number** 625633441905**Result** ✗ Failed**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Coolant level low.**MAJOR** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #8** 2019-03-21 15:24**MOT test number** 933086479890**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7**

2019-03-21 12:34

MOT test number

682682947785

Result**✗ Failed**

- MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Play in steering rack inner joint(s)
- MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Offside Rear Nail in tyre

MOT #6

2018-03-26 11:06

MOT test number

777096879628

Result**✓ Passed**

- Advice** Both front tyres below 3mm O/S has nail in
- Advice** Hand brake travel long

**MOT #5**

2018-03-23 16:09

MOT test number

725557227312

Result**✗ Failed****Fail** Windscreen wiper does not clear the windscreen effectively Both (8.2.2)**Fail** Brakes imbalanced across an axle 200 / 140 (3.7.B.5b)**Advice** Hand brake travel long**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Both front tyres below 3mm O/S has nail in**MOT #4**

2017-03-15 12:29

MOT test number

553979613749

Result**✓ Passed****Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear tyres have slight cracking in tread pattern**Advice** Offside Rear Nail in tyre**MOT #3**

2017-03-13 12:56

MOT test number

668673033738

Result**✗ Failed****Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Nail in tyre**Advice** Rear tyres have slight cracking in tread pattern**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #2	2016-03-18 15:46
MOT test number	367044615637
Result	✓ Passed
<div>Advice</div> Parking brake lever has little reserve travel (3.1.6b)	

MOT #1	2015-01-05 16:31
MOT test number	266515805086
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 September 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	WN61UUT
Plate since	2019-03-28
Current registration	WN61UUT
Plate since	2019-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-02
Last registration	2023-08-30
Complete history	See info



Registration #1	2011-11-02	13 mi
Registration #2	2015-01-05	28.191 mi
Registration #3	2016-03-18	37.791 mi
Registration #4	2017-03-13	44.496 mi
Registration #5	2017-03-15	44.498 mi
Registration #6	2018-03-23	48.383 mi
Registration #7	2018-03-26	48.384 mi
Registration #8	2019-03-21	54.836 mi
Registration #9	2019-03-22	55.337 mi
Registration #10	2019-03-23	55.337 mi
Registration #11	2019-03-24	55.337 mi
Registration #12	2019-03-25	55.337 mi
Registration #13	2019-03-26	55.337 mi
Registration #14	2019-03-27	55.337 mi
Registration #15	2019-03-28	55.337 mi
Registration #16	2019-03-29	55.337 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1354225