





report date: 2024-03-29

General information

Make	BMW
Model	520 520D SE
Colour	Silver
Year of manufacture	2007
Top speed	139 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/13



KH07MZL report date: 2024-03-29

MOT history

MOT expiry date	2025-02-21
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	32
Total items failed	6

MOT #18	2024-02-22 17:13
MOT test number	142887586269
Result	✓ Passed
Next expiry date	2025-02-21
Advice Brake pad wear light on dash	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #17		2023-02-21 17:20
MOT test	number	582318361803
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Offside Play in steering rack inner joint(s)	
Advice	Offside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))	
Advice	Brake pad warning light on	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT #16

MOT test number

973426802041

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

MOT test number

432084222935

Result

MOT #14

2021-04-06 06:55

MOT test number 889814810827

Result X Failed

Fail Offside Front Road wheel fractured (5.2.2 (a))

Fail
Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both front (5.3.4 (b) (ii))

Fail Offside Front Direction indicator incorrect colour (4.4.3 (a))

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #13 2020-04-07 12:44 **MOT** test number 796204169972 Result ✓ Passed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Nail in tyre

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12		2019-03-08 08:23
MOT test	number	521610494165
Result		✓ Passed
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excess	ive movement (5.3.4 (a)
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in excess	ssive movement (5.3.4

MOT #11	2018-03-14 09:36
MOT test number	256638959966
Result	✓ Passed
MOT #10	2017-03-16 12:14
MOT test number	949788577620
Result	✓ Passed
Advice Undertrays fitted	

MOT #9	2016-04-02 13:35
MOT test number	700447604051
Result	✓ Passed
Advice Nearside Drag link end ball joint has slight play (2.2.B.1f)	

MOT #8	2015-03-09 12:47
MOT test number	137918565021
Result	✓ Passed
MOT #7	2014-04-08 13:40
MOT test number	736438194007
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29



MOT #5		2013-05-01 10:57
MOT test	number	696851023145
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #4	2012-05-10 09:31
MOT test number	526791632104
Result	✓ Passed
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #3		2012-05-10 09:31
MOT test number		749901032173
Result		× Failed
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)	
Advice Front brake disc	worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2		2011-04-16 10:33
MOT test	number	155786401173
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Front discs slightly worn	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1		2010-05-12 14:07
MOT test	number	534022230148
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/13



KH07MZL report date: 2024-03-29

Tax & MOT check



✓ MOT

Tax expired: 1 January 2024

Tax status

Expires: 21 February 2025

Expired at 1 January 2024

Days left 120 days too late

MOT expiry date 21 February 2025

Full MOT history See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



KH07MZL report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



KH07MZL report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

KH07MZL

report date: 2024-03-29

For how long did the current and previous owner(s) have this BMW? How many owners did the Check it in the premium report and see all owner registrations. Download the full report here		ve?

	More info	>

Plate changes

See in this check if this BMW had different number plates.	
Number of plates	,
Correct registration	NE UK
Plate since	un Company
Current registration	NIE GIN
Plate since	maa

More info >

CarCheck.co.uk page 10/13



KH07MZL report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-05-11
Last registration	2024-02-22
Complete history	See info



Registration #1	2007-05-11	27 mi
Registration #2	2010-05-12	87.327 mi
Registration #3	2011-04-16	94.526 mi
Registration #4	2012-05-10	101.015 mi
Registration #5	2013-05-01	106.134 mi
Registration #6	2014-04-07	111.862 mi
Registration #7	2014-04-08	111.867 mi
Registration #8	2015-03-09	118.090 mi
Registration #9	2016-04-02	125.638 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 mg

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1510 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 13/1

Number of axles 2

Engine number 84326530