



report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Red
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-21
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	25
Total items failed	12

MOT #16	2024-03-16 08:05
MOT test number	100848161896
Result	✓ Passed
Next expiry date	2025-03-21

MOT #15	2023-03-13 16:21
MOT test number	805502724014
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14	2023-03-13 10:47
MOT test number	201695269826
Result	✗ Failed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #13	2022-03-18 13:17
MOT test number	528425429241
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Rear axle corroded just met mot requirements



MOT #12	2021-02-26 15:26
MOT test number	475318306641
Result	✓ Passed

MOT #11	2021-02-23 14:19
MOT test number	679139859661
Result	✗ Failed

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Registration plate lamp missing in the case of a single lamp or all lamps x2 (4.7.1 (b) (ii))
- Fail** Offside Rear Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Front Registration plate inscription illegible (0.1 (b))
- Fail** Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #10**

2020-02-27 09:55

MOT test number

464885112739

Result

✓ Passed

- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Exhaust has a minor leak of exhaust gases back box corroded (6.1.2 (a))

MOT #9

2019-02-22 12:13

MOT test number

979336235946

Result

✓ Passed

MOT #8

2018-03-16 11:35

MOT test number

145056313750

Result

✓ Passed

MOT #7

2017-03-22 14:22

MOT test number

947707596903

Result

✓ Passed



MOT #6	2016-09-23 15:50
MOT test number	260860416586
Result	✓ Passed
Advice	Exhaust back box deteriorating

MOT #5	2015-09-23 12:44
MOT test number	164985380754
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Front tyres wearing on edges
Advice	Exhaust back box deteriorating
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Oil leak

MOT #4	2015-09-23 10:27
MOT test number	162224196212
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Front tyres wearing on edges
Fail	Rear Exhaust system not adequately supported clamp missing (7.1.1)
Advice	Exhaust back box deteriorating
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Advice	Oil leak

MOT #3	2014-09-27 12:57
MOT test number	169620674290
Result	✓ Passed



MOT #2	2013-09-21 14:08
MOT test number	378624963420
Result	✓ Passed

MOT #1	2012-09-15 10:18
MOT test number	579629552224
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
21 March 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	MF59SNZ
Plate since	2024-03-29
Current registration	MF59SNZ
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-26
Last registration	2024-03-16
Complete history	See info



Registration #1	2009-09-26	6 mi
Registration #2	2012-09-15	26.849 mi
Registration #3	2013-09-21	37.238 mi
Registration #4	2014-09-27	49.376 mi
Registration #5	2015-09-23	58.963 mi
Registration #6	2015-09-23	58.963 mi
Registration #7	2016-09-23	62.569 mi
Registration #8	2017-03-22	66.704 mi
Registration #9	2018-03-16	75.596 mi
Registration #10	2019-03-22	85.277 mi
Registration #11	2019-03-22	85.277 mi
Registration #12	2019-03-22	85.277 mi
Registration #13	2019-03-22	85.277 mi
Registration #14	2019-03-22	85.277 mi
Registration #15	2019-03-22	85.277 mi
Registration #16	2019-03-22	85.277 mi
Registration #17	2019-03-22	85.277 mi
Registration #18	2019-03-22	85.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5187434