





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	E E220 CDI SE
Colour	Blue
Year of manufacture	2014
Top speed	141 mph
0 - 60 mph	8.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

	~		
10/1/	1	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2025-01-15
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	22
Total items failed	1

MOT #10	2024-01-12 16:11
MOT test number	836018732886
Result	✓ Passed
Next expiry date	2025-01-15

MOT #9		2023-01-16 14:04
MOT test	number	801565522552
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s	s (1.1.14 (a) (ii))
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))		
Advice	Play in steering rack inner joint(s)	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #8		2022-10-12 10:13
MOT test	number	548066081480
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Play in steering rack inner joint(s)	

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #7 2022-10-12 10:13

MOT test number 714936529066

Result × Failed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Play in steering rack inner joint(s)

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2021-10-18 13:03

MOT test number 327726762163

Result ✓ Passed

MOT #5 2020-10-08 12:43

MOT test number 895306254811

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2020-10-07 08:28

MOT test number 110286396549

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-04-04 10:42

MOT test number 438548123819

Result \(\sqrt{Passed} \)

MOT #2 2018-06-27 11:37

MOT test number 650008995774

MOT #1 2017-05-12 09:02

MOT test number 366258381879

Result \rightarrow Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 May
Days left	1
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How man MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Do report here .	

Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK SILE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-06-01
Last registration	2024-01-12
Complete history	See info



Registration #1	2014-06-01	19 mi
Registration #2	2017-05-12	23.522 mi
Registration #3	2018-06-27	47.934 mi
Registration #4	2019-04-04	70.488 mi
Registration #5	2020-10-07	104.723 mi
Registration #6	2020-10-08	104.817 mi
Registration #7		D.777 es
Registration #8		11.777 es
Registration #9		0.77 44
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
50295	
60482	
60501	
60566	
0567	
60569	
iew the complete MERCEDES-BENZ factory list for this ehicle here.	More info >

Dimensions & weight

Width	2071 mm
Height	1474 mm
Length	4879 mm
Wheel base	2874 mm
Kerb weight	1735 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	59 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	65192432365373

CarCheck.co.uk page 11/11