



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI (130BHP)
Colour	Blue
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	285 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-18
Pictures	6
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #18**

2021-10-07 10:47

MOT test number

639770317746

Result**✗ Failed**

- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Side repeater not working (4.4.1 (a) (ii))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Rear Registration plate inscription illegible (0.1 (b))
- Advice** Oil leak
- MAJOR** Headlamp light intensity severely reduced both front (4.1.4 (a))
- Advice** Rear axle corroded
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Nearside Rear Brake pipe excessively corroded marked in yellow (1.1.11 (c))
- MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
- MAJOR** Brake pedal has insufficient reserve travel (1.1.2 (a))
- Advice** Nearside Front tyre wearing on outer edge



MOT #17	2020-10-17 15:19
MOT test number	701447689750
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2020-10-16 16:01
MOT test number	349116952617
Result	✗ Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
DANGEROUS	Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
MAJOR	Nearside Side repeater light intensity significantly reduced (4.4.3 (a))
MAJOR	Service brake efficiency below requirements (1.2.2 (a) (i))
MAJOR	Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Upper Suspension arm ball joint excessively worn left (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Offside Side repeater incorrect colour (4.4.3 (a))

MOT #15	2019-10-19 12:05
MOT test number	691401855627
Result	✓ Passed

**MOT #14** 2018-10-06 12:31**MOT test number** 712315239805**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2017-10-21 11:39**MOT test number** 457921407821**Result** ✓ Passed**MOT #12** 2016-10-25 17:11**MOT test number** 278572687493**Result** ✓ Passed**Advice** Under covers engine covers**MOT #11** 2015-10-26 13:42**MOT test number** 366532652981**Result** ✓ Passed**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2014-10-18 13:44**MOT test number** 445911694296**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2013-10-16 16:15**MOT test number** 645739783293**Result** ✓ Passed

**MOT #8** 2013-10-14 10:58**MOT test number** 487287383277**Result** ✗ Failed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside rear brake binding (3.7.B.1)**MOT #7** 2012-08-29 10:44**MOT test number** 498262542239**Result** ✓ Passed**MOT #6** 2011-08-19 11:08**MOT test number** 136751531264**Result** ✓ Passed**MOT #5** 2010-08-19 11:40**MOT test number** 711471030235**Result** ✓ Passed**MOT #4** 2009-07-21 12:38**MOT test number** 113622909283**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #3

2008-08-21 11:38

MOT test number

162934138243

Result

✓ Passed

Advice

Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

MOT #2

2008-08-19 17:27

MOT test number

681642438273

Result

✗ Failed

Fail

Nearside Stop lamp not working (1.2.1b)

Advice

Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

Fail

Nearside Front constant velocity joint gaiter split (2.5.C.1a)

MOT #1

2007-04-16 13:37

MOT test number

362376207194

Result

✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 OV04FLJ
Plate since	2019-09-29
Current registration	 OV04FLJ
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-04-13
Last registration	2021-10-07
Complete history	See info



Registration #1	2004-04-13	18 mi
Registration #2	2007-04-16	46.001 mi
Registration #3	2008-08-19	53.049 mi
Registration #4	2008-08-21	53.051 mi
Registration #5	2009-07-21	61.531 mi
Registration #6	2010-08-19	70.799 mi
Registration #7	2011-08-19	78.964 mi
Registration #8	2012-08-29	89.136 mi
Registration #9	2013-10-14	95.724 mi
Registration #10	2013-10-16	95.741 mi
Registration #11	2014-05-20	95.777 mi
Registration #12	2014-05-20	95.777 mi
Registration #13	2014-05-20	95.777 mi
Registration #14	2014-05-20	95.777 mi
Registration #15	2014-05-20	95.777 mi
Registration #16	2014-05-20	95.777 mi
Registration #17	2014-05-20	95.777 mi
Registration #18	2014-05-20	95.777 mi
Registration #19	2014-05-20	95.777 mi
Registration #20	2014-05-20	95.777 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1462 mm
Length	4703 mm
Wheel base	2703 mm
Kerb weight	1565 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2

Engine number

AWX 445623