



HONDA




report date: 2024-03-28

General information

Make	HONDA
Model	INSIGHT IMA EX
Colour	Silver
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-12-11
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-19
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	16
Total items failed	2

MOT #14	2023-12-16 13:27
MOT test number	537077572988
Result	✓ Passed
Next expiry date	2024-12-19

MOT #13	2022-12-17 15:35
MOT test number	820014492453
Result	✓ Passed
Advice	Engine cover sheet fitted
Advice	Rear Brake disc worn, but not excessively both side (1.1.14 (a) (i))

MOT #12	2021-12-20 14:05
MOT test number	445426688090
Result	✓ Passed

MOT #11	2021-08-03 12:01
MOT test number	352424080318
Result	✓ Passed

**MOT #10** 2020-08-05 14:33**MOT test number** 383739395523**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2020-08-05 09:56**MOT test number** 604005834240**Result** ✗ Failed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #8** 2019-06-07 10:36**MOT test number** 559710840210**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #7** 2018-06-07 14:00**MOT test number** 133969813898**Result** ✓ Passed**Advice** Nearside Front Anti roll bar drop link upper gaiter partially split, not allowing ingress of dirt

**MOT #6** 2017-06-23 15:09**MOT test number** 861020448210**Result** ✓ Passed**Advice** Offside Rear Tyre wearing low on tread on inner edge**Advice** Nearside Rear Tyre has slight stepped wear to inner edge of tread**MOT #5** 2017-06-23 14:04**MOT test number** 970767347057**Result** ✗ Failed**Advice** Offside Rear Tyre wearing low on tread on inner edge**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Tyre has slight stepped wear to inner edge of tread**MOT #4** 2016-06-28 10:14**MOT test number** 348830218432**Result** ✓ Passed**Advice** Offside rear tyre wearing low on tread on inner edge**Advice** Corrosion developing on rear brake discs**MOT #3** 2015-06-24 11:52**MOT test number** 438725075108**Result** ✓ Passed**MOT #2** 2014-06-09 15:21**MOT test number** 677190464101**Result** ✓ Passed



MOT #1	2014-06-09 15:21
MOT test number	259260364113
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
19 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	KM11KFW
Plate since	2019-09-28
Current registration	KM11KFW
Plate since	2019-09-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-29
Last registration	2023-12-16
Complete history	See info



Registration #1	2011-06-29	13 mi
Registration #2	2014-06-09	33.861 mi
Registration #3	2015-06-24	41.119 mi
Registration #4	2016-06-28	44.499 mi
Registration #5	2017-06-23	49.814 mi
Registration #6	2017-06-23	49.814 mi
Registration #7	2018-06-07	53.228 mi
Registration #8	2019-06-07	55.963 mi
Registration #9	2020-06-07	58.700 mi
Registration #10	2021-06-07	61.437 mi
Registration #11	2022-06-07	64.174 mi
Registration #12	2023-06-07	66.911 mi
Registration #13	2024-06-07	69.648 mi
Registration #14	2025-06-07	72.385 mi
Registration #15	2026-06-07	75.122 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 2012079