





report date: 2024-03-29

### General information

Make	BMW
Model	428 428I M SPORT
Colour	Black
Year of manufacture	2015
Top speed	155 mph
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	241 BHP
Max. torque	350 Nm at 1.250 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



## Internet history

### Entry 2

Date	2024-02-05
Pictures	0
Listing price	<u>View report</u>

#### source: carcraft.co.uk

#### Entry 1

Date	2022-01-10	
Pictures	20	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-22
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	11
Total items failed	6

MOT #10	2024-01-23 15:14
MOT test number	963338022994
Result	✓ Passed
Next expiry date	2025-02-22

MOT #9	2024-01-23 12:00
MOT test number	453743504825
Result	<b>X</b> Failed
<b>Fail</b> Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2. <b>Advice</b> Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge. <b>Advice</b> Offside Rear Tyre has a cut but not deep enough to reach the ply or cords of cords showing at time of test) (5.2.3 (d) (i))	ge (5.2.3 (e))

MOT #8	2023-02-23 10:48
MOT test number	899678666508
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge Inner Edge. (5.2.3 (e))	

CarCheck.co.uk page 3/12



Result

LG15YNO report date: 2024-03-29

Passed

MOT #7 2023-02-23 10:48

**MOT test number** 632183898316

**Result** X Failed

Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge Inner Edge. (5.2.3 (e))

**Pass with rectification** Windscreen washer not working (3.5 (a))

MOT #6 2022-03-01 15:24

**MOT test number** 243919210937

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Tyre slightly damaged sidewall (5.2.3 (d) (ii))

MOT #5 2022-03-01 14:17

MOT test number 354134965547

Result X Failed

Fail Nearside Rear Tyre has ply or cords exposed also below 1.6 mm (5.2.3 (d) (ii))

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))

Advice Nearside Front Tyre slightly damaged sidewall (5.2.3 (d) (ii))

MOT #4 2021-03-25 14:07

**MOT test number** 937767709238

Result \rightarrow Passed

CarCheck.co.uk page 4/12



MOT #3

MOT test number

Result

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing tilin (1.1.13 (a) (ii))	
MOT #2	2019-01-17 13:27
MOT test number	679887008616
Result	✓ Passed
MOT #1	2018-03-26 16:16
MOT test number	478760173274
Result	<b>✓</b> Passed
Advice Under tray and engine cover fitted	

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Dailiage	-
Date	

Category

**Type** 

Damage 2

**Date** 

Category

**Type** 



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

o thier history	
For how long did the current and previous owner(s) have this BMW? How many owners defined the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	999-0-0
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-31
Last registration	2024-01-23
Complete history	See info



Registration #1	2015-03-31	11 mi
Registration #2	2018-03-26	12.287 mi
Registration #3	2019-01-17	15.252 mi
Registration #4	2020-03-19	16.258 mi
Registration #5	2021-03-25	30.645 mi
Registration #6		11.777 es
Registration #7	2022-03-01	33.107 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		D.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12




### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1825 mm
Height	1377 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1470 kg
Max. allowed weight	1990 kg

### Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4 pa	ge 12/12

Number of axles 2

Engine number A4171255