





report date: 2024-03-29

#### General information

| Make                | VOLVO            |
|---------------------|------------------|
| Model               | XC40 T3 MOMENTUM |
| Colour              | Red              |
| Year of manufacture | 2018             |
| Top speed           | 124 mph          |
| Gearbox             | 6 speed Manual   |

## Engine & fuel consumption

| Power                | 154 BHP             |
|----------------------|---------------------|
| Max. torque          | 265 Nm at 1.850 rpm |
| Engine capacity      | 1.477 cc            |
| Cylinders            | 3                   |
| Fuel type            | Petrol              |
| Consumption combined | 2.8 mpg             |
| CO2 emission         | 144 g/km            |
| CO2 label            | F                   |



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-02-06


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

| MOT expiry date    | 2024-10-19 |
|--------------------|------------|
| MOT pass rate      | 60 %       |
| MOT passed         | 3          |
| Failed MOT tests   | 2          |
| Total advice items | 11         |
| Total items failed | 2          |

| MOT #5   | 2023-10-16 14:45 |
|--|------------------|
| MOT test number  | 754525644488     |
| Result   | <b>✓</b> Passed  |
| Next expiry date   | 2024-10-19       |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) | (ii))            |


| MOT #4   |   | 2023-10-16 13:37 |
|--|---|------------------|
| MOT test   | number  | 418470128883     |
| Result   |   | <b>X</b> Failed  |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))  |   |                  |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |   |                  |
| <b>Fail</b> Ro   | ear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |                  |

| MOT #3   |   | 2022-10-11 12:17 |
|----------|---|------------------|
| MOT test | number  | 322656827319     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Rear Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))  |                  |
| Advice   | Nearside Front strut top bearing slightly noisy               |                  |
| Advice   | Nearside Rear Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii)) |                  |

CarCheck.co.uk page 3/11



report date: 2024-03-29



| MOT #1  | 2021-10-08 11:26 |
|---|------------------|
| MOT test number   | 100174307483     |
| Result  | <b>✓</b> Passed  |
| Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e)) |                  |

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



| Tax status       | Valid until 1 February |
|------------------|------------------------|
| Days left        | 277                    |
| MOT expiry date  | 19 October 2024        |
| Full MOT history | See MOT history        |

#### Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

| _      |           |
|--------|-----------|
| Owner  | history   |
| OWITCE | ilistoi y |

| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full  |             |
|--|-------------|
|  |             |
| THE STATE OF THE S |             |
| ***************************************  |             |
| ***************************************  |             |
| ***************************************  |             |
| ***************************************  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLVO had different number plates.   |             |
| Number of plates   |             |
| Current registration   | NE NE       |
| Plate since  |             |
| Current registration   | UK UK       |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 7          |
| First mileage registration | 2018-10-20 |
| Last registration          | 2023-10-16 |
| Complete history           | See info   |



| Registration #1 | 2018-10-20 | 9 mi      |
|-----------------|------------|-----------|
| Registration #2 |            | 77,777 66 |
| Registration #3 | 2021-10-08 | 16.906 mi |
| Registration #4 | 2022-10-11 | 24.896 mi |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 71.777 66 |
| Registration #7 |            | 11,777 mi |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 60295 |                 |
| 60482 |                 |
| 60501 |                 |
| 60566 |                 |
| 60567 |                 |
| 60569 |                 |

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 97%             |
| Children       | 87%             |
| Pedestrian     | 71%             |
| Safety systems | 76%             |
| Overall rating | 86%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1910 mm |
|---------------------|---------|
| Height              | 1658 mm |
| Length              | 4425 mm |
| Kerb weight         | 1497 kg |
| Max. allowed weight | 2060 kg |

# Additional information

| Fuel delivery                   | Direct Injection   |
|---------------------------------|--------------------|
| Number of doors                 | 5                  |
| Number of seats                 | 5                  |
| Number of axles                 | 2                  |
| Engine number<br>Carcheck.co.uk | 7026458 page 11/11 |