





report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI ALLURE
Colour	Grey
Year of manufacture	2011
Top speed	114 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP	
Max. torque	230 Nm at 1.750 rpm	
Engine capacity	1.560 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	52.3 mpg	
Consumption extra urban	76.4 mpg	
Consumption combined	65.7 mpg	
CO2 emission	113 g/km	
CO2 label	С	



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-09-02


Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-08
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	15
Total items failed	7

MOT #14		2024-04-06 09:08
MOT test	number	203151293998
Result		✓ Passed
Next expi	ry date	2025-04-08
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice All front and rear suspension and all associated components have rust and chassis and body		

MOT #13		2023-04-06 08:58
MOT test	number	759980478441
Result		✓ Passed
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

CarCheck.co.uk page 3/13



MOT test number

Result

Advice Exhaust middle section heatshield missing

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT test number

681821047207

Result

Pass with rectification
Front Windscreen wiper does not clear the windscreen effectively x2 (3.4 (b) (ii))

Advice
Exhaust middle section heatshield missing

Pass with rectification
Offside Headlamp aim projected beam image is obviously incorrect bulb incorrect (4.1.2 (c))

Advice
Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #10

MOT test number

Result

Advice Small chip in zone A of windscreen

Advice Items removed from driver's view prior to test

 MOT #9
 2020-03-26 10:15

 MOT test number
 532472195288

 Result
 ✓ Passed

 MOT #8
 2019-03-27 13:27

 MOT test number
 548022298271

 Result
 ✓ Passed

 Advice
 Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



MOT #7 2018-04-09 12:37 **MOT test number** 563225003370 Result ✓ Passed MOT #6 2018-04-05 16:06 **MOT** test number 140984164896 Result × Failed Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b) Fail Offside Stop lamp not working (1.2.1b) **Advice** Nearside Front Tyre worn close to the legal limit 2 mm (205/45/17 h) (4.1.E.1) Offside Headlamp aim beam image obviously incorrect (1.8.A.1b) Fail Fail Exhaust system not adequately supported front and rear brackets broken (7.1.1)

MOT #5	2017-07-17 12:20
MOT test number	811437962409
Result	✓ Passed
MOT #4	2016-04-18 15:38
MOT test number	734966893481
Result	✓ Passed
MOT #3	2015-03-17 13:29
MOT test number	997786775043
Result	✓ Passed
MOT #2	2015-03-17 13:29
MOT test number	809816775021
Result	× Failed
Pass with rectification Nearside Stop lamp not working (1.2.1b)	

CarCheck.co.uk page 5/13



MOT #1 2014-03-17 10:33

MOT test number 306146174088

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

o met motory	
For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NIE.
Plate since	
Current registration	IIK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-04-11
Last registration	2024-04-06
Complete history	See info



Registration #1	2011-04-11	11 mi
Registration #2	2014-03-17	34.275 mi
Registration #3	2015-03-17	43.224 mi
Registration #4	2016-04-18	53.702 mi
Registration #5	2017-07-17	63.551 mi
Registration #6	2018-04-05	64.921 mi
Registration #7	2018-04-09	64.921 mi
Registration #8	2019-03-27	79.692 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1328 kg
Max. allowed weight	1718 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1

Number of axles 2

Engine number JBDL0034735