



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE ACENTA
Colour	Grey
Year of manufacture	2011
Top speed	108 mph
0 - 60 mph	11.7 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	153 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	52.3 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2


Date	2023-04-01
Pictures	9
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

Entry 1

Date	2021-01-21
Pictures	17
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://yesauto.com)



MOT history

MOT expiry date	2025-04-03
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	23
Total items failed	11

MOT #15	2024-03-27 12:57
MOT test number	656566825883
Result	✓ Passed
Next expiry date	2025-04-03
Advice	Items removed from driver's view prior to test
Advice	Auxilliary drive belt worn/damaged
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Driver seat slight play
Advice	Rear Suspension component corroded but not seriously weakened Axle (5.3.3 (b) (i))

**MOT #14**

2024-03-21 16:51

**MOT test number**

558147542434

**Result****✗ Failed****Advice** Rear Suspension component corroded but not seriously weakened Axle (5.3.3 (b) (i))**Advice** Driver seat slight play**Fail** Drive belt so worn it is likely to fail (6.1.7 (c) (ii))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Items removed from driver's view prior to test**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #13**

2023-04-04 10:29

**MOT test number**

331077216860

**Result****✓ Passed****MOT #12**

2023-04-03 11:36

**MOT test number**

181542211100

**Result****✗ Failed****Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Emissions unable to be completed due to exhaust leak (8.2.1.2 (d))

**MOT #11** 2022-09-28 12:26**MOT test number** 154934324120**Result** ✓ Passed**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Oil leak, but not excessive seal? (8.4.1 (a) (i))**MOT #10** 2021-09-21 10:41**MOT test number** 705168109777**Result** ✓ Passed**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Oil leak, but not excessive from gearbox (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #9** 2020-09-25 10:51**MOT test number** 160361388785**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-09-25 10:51**MOT test number** 542999781161**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2019-09-21 12:52**MOT test number** 791134881374**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn outer edge/central (5.2.3 (e))**MOT #6** 2018-09-05 16:02**MOT test number** 239697948827**Result** ✓ Passed**MOT #5** 2017-09-18 14:24**MOT test number** 615104473654**Result** ✓ Passed**MOT #4** 2017-09-18 11:43**MOT test number** 996093308355**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #3** 2016-07-05 11:02**MOT test number** 995975962645**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-09-10 16:59**MOT test number** 987093854290**Result** ✓ Passed



MOT #1	2014-09-05 11:46
MOT test number	317698144412
Result	✗ Failed
Fail	Nearside Front Shock absorber has a serious fluid leak (2.7.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
3 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	3 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-16
Last registration	2024-03-27
Complete history	<a href="#">See info</a>



Registration #1	2011-09-16	12 mi
Registration #2	2014-09-05	25.719 mi
Registration #3	2014-09-10	25.736 mi
Registration #4	2016-07-05	38.663 mi
Registration #5	2017-09-18	47.597 mi
Registration #6	2017-09-18	47.597 mi
Registration #7	2018-09-05	55.102 mi
Registration #8	2019-09-21	67.234 mi
Registration #9	2020-09-25	70.440 mi
Registration #10	2020-09-25	70.440 mi
Registration #11	2020-09-25	70.440 mi
Registration #12	2020-09-25	70.440 mi
Registration #13	2020-09-25	70.440 mi
Registration #14	2020-09-25	70.440 mi
Registration #15	2020-09-25	70.440 mi
Registration #16	2020-09-25	70.440 mi
Registration #17	2020-09-25	70.440 mi
Registration #18	2020-09-25	70.440 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1690 mm
Height	1550 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1165 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	34550B