





report date: 2024-03-29

## General information

| Make                | VOLKSWAGEN     |
|---------------------|----------------|
| Model               | GOLF MATCH TDI |
| Colour              | Blue           |
| Year of manufacture | 2019           |
| Top speed           | 123 mph        |
| 0 - 100 km/h        | 10.2 seconds   |
| Gearbox             | 6 speed Manual |

# Engine & fuel consumption

| Power                   | 85 kW / 116 HP / 114 BHP |
|-------------------------|--------------------------|
| Max. torque             | 250 Nm at 1.500 rpm      |
| Engine capacity         | 1.598 cc                 |
| Cylinders               | 4                        |
| Fuel type               | Diesel                   |
| Consumption city        | 50.0 mpg                 |
| Consumption extra urban | 61.9 mpg                 |
| Consumption combined    | 57.7 mpg                 |
| CO2 emission            | 108 g/km                 |
| CO2 label               | В                        |



CarCheck.co.uk page 1/10



# Internet history

## Entry 1

Date 2022-07-15

Pictures 30

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date    | 2024-06-13 |
|--------------------|------------|
| MOT pass rate      | 67 %       |
| MOT passed         | 2          |
| Failed MOT tests   | 1          |
| Total advice items | 2          |
| Total items failed | 2          |

| MOT #3  | 2023-06-14 16:01 |
|---|------------------|
| MOT test number   | 662069446818     |
| Result  | ✓ Passed         |
| Next expiry date  | 2024-06-13       |
| Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #2  | 2023-06-14 13:36 |
|---|------------------|
| MOT test number   | 295272942897     |
| Result  | 🗙 Failed         |
| Fail Offside Front Headlamp aim unable to be tested (4.1.2 (b))                         |                  |
| Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))     |                  |
| Fail Offside Front Headlamp not working on dipped beam headlight bulb inop (4.1.1 (a) ( | (ii))            |

| MOT #1          | 2022-06-01 16:28 |
|-----------------|------------------|
| MOT test number | 938774857750     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/10



## Tax & MOT check



| Tax status       | Valid until 1 October |
|------------------|-----------------------|
| Days left        | 155                   |
| MOT expiry date  | 13 June 2024          |
| Full MOT history | See MOT history       |

## Tax calculation

| 1 10 10 10 1   |            |
|--|------------|
| Vehicle class  | 49         |
| Band   | F          |
| First licence fee (12 months)                        | £ 185,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 210,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |

CarCheck.co.uk page 4/10



HD19KCO


report date: 2024-03-29

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

| Date     |  |
|----------|--|
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



HD19KCO

report date: 2024-03-29

More info >

# Owner history

| , ,  |             |
|--|-------------|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here. |             |
| *********  |             |
|  |             |
| ***************************************  |             |
| ********   |             |
|  |             |
| *************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLKSWAGEN had different number plates.  |             |
| Number of plates   | ,           |
| Current registration   | AIS UK      |
| Plate since  |             |
| Current registration   | NIP.<br>UK  |
| Plate since  |             |
|  |             |

CarCheck.co.uk page 7/10



## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

**Contact info** 

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 5          |
| First mileage registration | 2019-06-03 |
| Last registration          | 2023-06-14 |
| Complete history           | See info   |



| Registration #1 | 2019-06-03 | 10 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2022-06-01 | 60.733 mi |
| Registration #3 |            | 11.177 es |
| Registration #4 |            | 71.777 es |
| Registration #5 |            | 11.777 es |

More info >

CarCheck.co.uk page 9/10




Car features

| 50225 | Air conditionir |
|-------|-----------------|
| 50295 |                 |
| 50482 |                 |
| 60501 |                 |
| 60566 |                 |
| 0567  |                 |
| 60569 |                 |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 94%             |
| Children       | 89%             |
| Pedestrian     | 65%             |
| Safety systems | 71%             |
| Overall rating | 85%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 2027 mm |
|---------------------|---------|
| Height              | 1492 mm |
| Length              | 4258 mm |
| Wheel base          | 2620 mm |
| Kerb weight         | 1255 kg |
| Max. allowed weight | 1860 kg |

# Additional information

| Fuel tank capacity | 50 I |            |
|--------------------|------|------------|
| Number of seats    | 5    |            |
| Number of axles    | 2    |            |
| CarChack could     |      | nage 10/10 |

CarCheck.co.uk page 10/10

**Engine number** 

DGTE812355