



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Silver
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-02-13
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-03
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	17
Total items failed	5

MOT #16 2023-11-03 19:10

MOT test number 841615228331

Result ✓ Passed

Next expiry date 2024-11-03

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #15 2022-11-04 16:41

MOT test number 411169313049

Result ✓ Passed

MOT #14 2021-12-09 12:28

MOT test number 759861106982

Result ✓ Passed

Minor Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #13** 2020-12-30 12:02**MOT test number** 518250995871**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2020-12-30 12:02**MOT test number** 244329523143**Result** ✗ Failed**Pass with rectification** Front Registration plate inscription illegible (0.1 (b))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Front Headlamp has a product on the lens so that the light output is severely reduced Both (4.1.4 (b))**MOT #11** 2020-01-04 11:30**MOT test number** 106631273191**Result** ✓ Passed**MOT #10** 2019-01-17 09:52**MOT test number** 154239352783**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Drive shaft joint constant velocity boot slightly deteriorated**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2018-01-17 08:56**MOT test number** 159850586577**Result** ✓ Passed**MOT #8** 2016-06-22 09:38**MOT test number** 184986805498**Result** ✓ Passed**MOT #7** 2015-05-29 13:12**MOT test number** 576659545165**Result** ✓ Passed**MOT #6** 2013-11-30 09:57**MOT test number** 615074533332**Result** ✓ Passed**MOT #5** 2013-11-30 09:57**MOT test number** 307824333311**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2012-12-01 11:56**MOT test number** 366676332323**Result** ✓ Passed**MOT #3** 2012-11-24 10:05**MOT test number** 156019322397**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)



MOT #2	2011-11-29 16:28
MOT test number	677523631394
Result	✓ Passed

MOT #1	2011-08-01 12:17
MOT test number	217853911241
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
3 November 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-04
Last registration	2023-11-03
Complete history	See info



Registration #1	2008-09-04	13 mi
Registration #2	2011-08-01	28.120 mi
Registration #3	2011-11-29	29.562 mi
Registration #4	2012-11-24	39.518 mi
Registration #5	2012-12-01	39.727 mi
Registration #6	2013-11-30	50.953 mi
Registration #7	2015-05-29	66.327 mi
Registration #8	2016-06-22	76.700 mi
Registration #9	2018-01-17	92.800 mi
Registration #10	2019-05-29	101.377 mi
Registration #11	2019-05-29	101.377 mi
Registration #12	2019-05-29	101.377 mi
Registration #13	2019-05-29	101.377 mi
Registration #14	2019-05-29	101.377 mi
Registration #15	2019-05-29	101.377 mi
Registration #16	2019-05-29	101.377 mi
Registration #17	2019-05-29	101.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	131943
---------------	--------