



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D3 DRIVE ES
Colour	Grey
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-24
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	46
Total items failed	2

MOT #14	2024-01-25 11:49
MOT test number	752714755115
Result	✓ Passed
Next expiry date	2025-01-24
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Play in steering rack inner joint(s)
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13**

2024-01-24 10:26

**MOT test number**

710094842531

**Result****✗ Failed**

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Nearside Headlamp aim too high (4.1.2 (a))

**MOT #12**

2023-01-18 14:47

**MOT test number**

222463024173

**Result****✓ Passed**

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Under trays engine covers covering mot items
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Suspension parts corroded

**MOT #11** 2023-01-18 11:53**MOT test number** 311173015095**Result** ✗ Failed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Under trays engine covers covering mot items**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**DANGEROUS** Nearside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Suspension parts corroded**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**MOT #10** 2022-01-25 09:45**MOT test number** 215416763618**Result** ✓ Passed**MOT #9** 2020-12-11 12:01**MOT test number** 726373189631**Result** ✓ Passed**MOT #8** 2020-01-08 14:42**MOT test number** 187645722105**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2020-01-06 10:29**MOT test number** 297908259289**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-01-09 07:56**MOT test number** 155691472905**Result** ✓ Passed**MOT #5** 2019-01-09 07:56**MOT test number** 712751670019**Result** ✗ Failed**Pass with rectification** Rear Registration plate inscription illegible dirty (0.1 (b))**MOT #4** 2018-01-05 15:02**MOT test number** 258680138522**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2018-01-04 11:41**MOT test number** 655902270035**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2016-04-14 13:15
MOT test number	238440803774
Result	✓ Passed
Advice	Child seat fitted preventing full inspection of adult seatbelt
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2015-03-18 13:59
MOT test number	835537075010
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
24 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	24 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-30
Last registration	2024-01-25
Complete history	<a href="#">See info</a>



Registration #1	2012-03-30	10 mi
Registration #2	2015-03-18	19.853 mi
Registration #3	2016-04-14	36.390 mi
Registration #4	2018-01-04	69.511 mi
Registration #5	2018-01-05	69.512 mi
Registration #6	2019-01-09	86.636 mi
Registration #7	2019-01-09	86.636 mi
Registration #8	2020-01-06	103.053 mi
Registration #9	2020-01-06	103.053 mi
Registration #10	2020-01-06	103.053 mi
Registration #11	2020-01-06	103.053 mi
Registration #12	2020-01-06	103.053 mi
Registration #13	2020-01-06	103.053 mi
Registration #14	2020-01-06	103.053 mi
Registration #15	2020-01-06	103.053 mi
Registration #16	2020-01-06	103.053 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1756 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1161516