



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 2


Date	2021-10-30
Pictures	27
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-10-29
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #22</b>	2022-10-17 07:43
<b>MOT test number</b>	300884252055
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-10-19
<b>Advice</b>	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

<b>MOT #21</b>	2021-10-20 08:44
<b>MOT test number</b>	127983221021
<b>Result</b>	✓ Passed

<b>MOT #20</b>	2020-10-01 11:53
<b>MOT test number</b>	738633713177
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
<b>Advice</b>	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

<b>MOT #19</b>	2019-10-15 12:31
<b>MOT test number</b>	395433437519
<b>Result</b>	✓ Passed

**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**Advice** Play in steering rack inner joint(s) both

**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**Advice** Central Rear Exhaust mounting defective (6.1.2 (a))

**MOT #18**

2019-10-05 09:58

**MOT test number**

937275550210

**Result****✗ Failed**

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Central Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Fail** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Play in steering rack inner joint(s) both

**MOT #17**

2018-09-27 14:14

**MOT test number**

750475888806

**Result****✓ Passed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2018-09-26 12:14

**MOT test number**

994182457072

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Front Track rod end ball joint has excessive play both side (2.1.3 (b) (i))

**MOT #15** 2017-10-18 14:43**MOT test number** 793549064043**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2017-10-17 16:21**MOT test number** 964681958879**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Battery insecure (1.9.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear fog lamp not working (1.3.2b)**MOT #13** 2017-01-04 12:40**MOT test number** 561184995820**Result** ✓ Passed**MOT #12** 2016-01-09 11:19**MOT test number** 367911950979**Result** ✓ Passed

**MOT #11**

2014-07-10 11:07

**MOT test number**

147291094148

**Result**

✓ Passed

**Advice** Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Exhaust centre bracket deteriorated but not insecure**Advice** Offside Inner Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Inner Front Brake pad(s) wearing thin (3.5.1g)**MOT #10**

2014-07-10 11:07

**MOT test number**

799401694120

**Result**

✗ Failed

**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Inner Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Inner Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Exhaust centre bracket deteriorated but not insecure**MOT #9**

2013-07-24 10:45

**MOT test number**

907945403221

**Result**

✓ Passed

**MOT #8** 2013-07-23 10:23**MOT test number** 819284403247**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #7** 2012-08-02 14:14**MOT test number** 529355612228**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #6** 2012-08-02 09:57**MOT test number** 659585512275**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**MOT #5** 2011-07-23 10:58**MOT test number** 198454601206**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



**MOT #4** 2011-07-23 10:58**MOT test number** 767644301211**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #3** 2010-07-27 12:14**MOT test number** 334198100443**Result** ✓ Passed**MOT #2** 2009-07-25 11:57**MOT test number** 840066509271**Result** ✓ Passed**MOT #1** 2009-07-25 11:57**MOT test number** 181086909208**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-08-03
Last registration	2022-10-17
Complete history	<a href="#">See info</a>



Registration #1	2006-08-03	6 mi
Registration #2	2009-07-25	15.093 mi
Registration #3	2010-07-27	21.202 mi
Registration #4	2011-07-23	28.630 mi
Registration #5	2012-08-02	34.134 mi
Registration #6	2012-08-02	34.134 mi
Registration #7	2013-07-23	38.335 mi
Registration #8	2013-07-24	38.350 mi
Registration #9	2014-07-10	44.183 mi
Registration #10	2016-01-09	57.904 mi
Registration #11	2017-01-04	70.131 mi
Registration #12	2018-01-04	82.358 mi
Registration #13	2019-01-04	94.585 mi
Registration #14	2020-01-04	106.812 mi
Registration #15	2021-01-04	119.039 mi
Registration #16	2022-01-04	131.266 mi
Registration #17	2023-01-04	143.493 mi
Registration #18	2024-01-04	155.720 mi
Registration #19	2025-01-04	167.947 mi
Registration #20	2026-01-04	180.174 mi
Registration #21	2027-01-04	192.401 mi
Registration #22	2028-01-04	204.628 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1275 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX6N2815197