





report date: 2024-03-28

General information

Make	AUDI
Model	A6 T FSI SE
Colour	Silver
Year of manufacture	2008
Top speed	138 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	279 Nm at 1.800 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.5 mpg
CO2 emission	192 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-27

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-09-15
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	19
Total items failed	8

MOT #17		2023-09-05 09:32
MOT test	number	625455743300
Result		✓ Passed
Next expi	ry date	2024-09-15
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #16	2022-09-05 14:39
MOT test number	701018024513
Result	✓ Passed

MOT #15	2022-08-15 13:47
MOT test number	532194451714
Result	X Failed

Fail Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #14 2021-09-16 14:48

MOT test number 749852237816

Result
✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2021-09-15 15:34

MOT test number 871538636917

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Front Exhaust has a major leak of exhaust gases downpipe (6.1.2 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2021-02-23 06:11

MOT test number 408530670366

Result \(\sqrt{Passed} \)

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both upper arms inner bushes slightly deteriorated/cracking (5.3.4 (a) (i))

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both upper arms inner bushes slightly deteriorated/cracking (5.3.4 (a) (i))

MOT #11 2019-07-02 15:11

MOT test number 881764252706

Result \(\sqrt{Passed} \)

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin Both (1.1.13 (a) (ii))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



Result

OEO8AHN

report date: 2024-03-28

Passed

MOT #10

MOT test number

Result

Advice
Rear Brake pad(s) wearing thin (3.5.1g)

Advice
Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #9
 2017-05-22 08:28

 MOT test number
 235575629479

 Result
 ✓ Passed

 MOT #8
 2016-05-25 14:01

 MOT test number
 377793171687

 MOT #7
 2016-05-25 09:38

 MOT test number
 527713540305

Result × Failed

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #6

MOT test number

227622045457

Result

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5		2014-05-09 12:45
MOT test	number	235489924141
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
Advice	Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)	

Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)		
MOT #4		2013-04-26 14:56
MOT test number		819276813140
Result		✓ Passed
MOT #3		2012-07-25 10:20
MOT test number		268227002287
Result		✓ Passed
MOT #2		2011-07-18 15:04
MOT test number		426249191181
Result		✓ Passed
MOT #1		2011-07-18 15:04
MOT test number		558539491162
Result		× Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)	

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check





Expires: 15 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NIP.
Plate since	
Current registration	NIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



OEO8AHN

report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-05-15
Last registration	2023-09-05
Complete history	See info



Registration #1	2008-05-15	10 mi
Registration #2	2011-07-18	38.988 mi
Registration #3	2012-07-25	59.457 mi
Registration #4	2013-04-26	76.680 mi
Registration #5	2014-05-09	80.897 mi
Registration #6	2015-05-22	86.231 mi
Registration #7	2016-05-25	90.989 mi
Registration #8	2016-05-25	90.992 mi
Registration #9	2017-05-22	96.671 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,700 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4933 mm
Wheel base	2760 mm
Kerb weight	1540 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1

Number of axles 2

Engine number BPJ 090325