



SM59MKE

report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Grey
Year of manufacture	-
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-05-26
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #18 2022-06-27 16:18

MOT test number 169309708144

Result ✓ Passed

Next expiry date 2023-07-19

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre wearing on outer edge, not to excess. 175/65/15 (5.2.3 (e))
- Advice** Nearside Front Inner Inner wheel arch cover missing.
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Bottom ball joint boot deteriorated.
- Advice** Exhaust blow possibly manifold.
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Radiator only held in by cables and bungy cord, not secure at all.



MOT #17

2022-06-27 11:39

MOT test number

698548868655

Result

✗ Failed

MAJOR Rear Reversing lamp inoperative (4.6.1 (a))**Advice** Nearside Front Inner Inner wheel arch cover missing.**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Bottom ball joint boot deteriorated.**MAJOR** Front Windscreen washer not working (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre wearing on outer edge, not to excess. 175/65/15 (5.2.3 (e))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Exhaust blow possibly manifold.**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Radiator only held in by cables and bungy cord, not secure at all.**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Front Windscreen wiper not working (3.4 (a))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively Blade split. (3.4 (b) (ii))

MOT #16

2021-07-20 11:43

MOT test number

425557135467

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #15	2021-07-20 11:43
MOT test number	722405957326
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))

MOT #14	2020-07-15 11:36
MOT test number	796397497469
Result	✓ Passed

MOT #13	2020-07-15 11:36
MOT test number	402441541252
Result	✗ Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #12	2019-05-03 13:18
MOT test number	732614614701
Result	✓ Passed

MOT #11	2019-04-30 09:02
MOT test number	483139945570
Result	✗ Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Offside Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #10	2018-04-13 10:57
MOT test number	517049703866
Result	✓ Passed

**MOT #9** 2016-10-26 10:30**MOT test number** 686307535333**Result** ✓ Passed

- Advice** Oil leak engine sump pan leaking oil
- Advice** Advise exhaust rear section thru to second skin and outer cover loose
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #8 2016-10-26 08:54**MOT test number** 343179787955**Result** ✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Oil leak engine sump pan leaking oil
- Fail** Nearside Front Headlamp incorrect colour (1.7.5b)
- Fail** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt top ball joint cover (2.4.G.2)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Advise exhaust rear section thru to second skin and outer cover loose
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Front Headlamp incorrect colour (1.7.5b)

MOT #7 2015-10-17 10:53**MOT test number** 951506244208**Result** ✓ Passed**MOT #6** 2015-10-17 08:52**MOT test number** 973390724891**Result** ✗ Failed

- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)

**MOT #5** 2014-10-21 14:32**MOT test number** 828874594298**Result** ✓ Passed**MOT #4** 2014-10-21 13:34**MOT test number** 277504594272**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2013-10-29 16:04**MOT test number** 379112203343**Result** ✓ Passed**MOT #2** 2013-10-28 13:43**MOT test number** 437061503357**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #1** 2012-12-20 12:36**MOT test number** 467655652444**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-12-30
Last registration	2022-06-27
Complete history	See info



Registration #1	2009-12-30	29 mi
Registration #2	2012-12-20	19.159 mi
Registration #3	2013-10-28	26.375 mi
Registration #4	2013-10-29	26.375 mi
Registration #5	2014-10-21	49.645 mi
Registration #6	2014-10-21	49.645 mi
Registration #7	2015-10-17	70.316 mi
Registration #8	2015-10-17	70.316 mi
Registration #9	2016-10-26	85.736 mi
Registration #10	2016-10-26	85.736 mi
Registration #11	2016-10-26	85.736 mi
Registration #12	2016-10-26	85.736 mi
Registration #13	2016-10-26	85.736 mi
Registration #14	2016-10-26	85.736 mi
Registration #15	2016-10-26	85.736 mi
Registration #16	2016-10-26	85.736 mi
Registration #17	2016-10-26	85.736 mi
Registration #18	2016-10-26	85.736 mi
Registration #19	2016-10-26	85.736 mi
Registration #20	2016-10-26	85.736 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694