



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	White
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-11-24
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-14
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	8
Total items failed	5

MOT #14	2023-10-04 16:38
MOT test number	676228175538
Result	✓ Passed
Next expiry date	2024-10-14

MOT #13	2022-10-11 12:56
MOT test number	119566845403
Result	✓ Passed

MOT #12	2021-10-15 11:28
MOT test number	474480000355
Result	✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front & rear (1.1.14 (a) (ii))
- Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.5mm & bald on inner edge (5.2.3 (e))

**MOT #11** 2021-10-15 11:28**MOT test number** 962130744228**Result** ✗ Failed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front & rear (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.5mm & bald on inner edge (5.2.3 (e))**Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #10** 2020-08-28 15:25**MOT test number** 392621014314**Result** ✓ Passed**MOT #9** 2019-04-15 15:38**MOT test number** 311201372312**Result** ✓ Passed**MOT #8** 2018-05-14 12:28**MOT test number** 452405723880**Result** ✓ Passed**MOT #7** 2018-05-14 08:18**MOT test number** 710718791728**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #6	2017-05-26 14:29
---------------	------------------

MOT test number	152728725425
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2016-05-21 12:12
---------------	------------------

MOT test number	943901702081
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-05-21 12:12
---------------	------------------

MOT test number	536656610264
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	--

MOT #3	2015-05-12 13:37
---------------	------------------

MOT test number	835882635118
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-05-12 12:07
---------------	------------------

MOT test number	758432234118
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-05-13 12:15
---------------	------------------

MOT test number	725713333163
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 October 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	14 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-15
Last registration	2023-10-04
Complete history	See info



Registration #1	2010-05-15	6 mi
Registration #2	2013-05-13	14.065 mi
Registration #3	2014-05-12	17.808 mi
Registration #4	2015-05-12	24.754 mi
Registration #5	2016-05-21	32.707 mi
Registration #6	2016-05-21	32.707 mi
Registration #7	2017-05-26	42.681 mi
Registration #8	2018-05-14	55.351 mi
Registration #9	2019-05-20	55.351 mi
Registration #10	2019-05-20	55.351 mi
Registration #11	2019-05-20	55.351 mi
Registration #12	2019-05-20	55.351 mi
Registration #13	2019-05-20	55.351 mi
Registration #14	2019-05-20	55.351 mi
Registration #15	2019-05-20	55.351 mi
Registration #16	2019-05-20	55.351 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1299 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	181935