



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D3 ES
Colour	Grey
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	67.3 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-16
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-29
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	17
Total items failed	4

MOT #15	2023-11-30 10:52
MOT test number	861774111910
Result	✓ Passed
Next expiry date	2024-11-29
Advice	Offside Play in steering rack inner joint(s)

MOT #14	2022-11-07 10:01
MOT test number	580158039852
Result	✓ Passed

MOT #13	2021-11-30 15:05
MOT test number	364371864121
Result	✓ Passed

MOT #12	2020-10-28 14:29
MOT test number	564219733011
Result	✓ Passed
Advice	Offside Front front Side marker light
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2020-10-28 14:29**MOT test number** 786802158771**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Front front Side marker light**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2019-11-21 11:16**MOT test number** 270917700991**Result** ✓ Passed**MOT #9** 2019-10-26 08:49**MOT test number** 628195477885**Result** ✗ Failed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #8** 2018-10-31 17:16**MOT test number** 380486716568**Result** ✓ Passed**MOT #7** 2018-05-17 09:01**MOT test number** 741731710081**Result** ✓ Passed**Advice** Engine cover and under trays fitted obscuring some testable components**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2017-05-17 08:39**MOT test number** 108973179359**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Engine cover and under tray fitted obscuring some testable components**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2016-05-18 09:24**MOT test number** 559618461016**Result** ✓ Passed**Advice** Engine cover and undertrays fitted**MOT #4** 2015-05-13 11:25**MOT test number** 457063035186**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2014-05-28 15:57**MOT test number** 459288644190**Result** ✓ Passed**MOT #2** 2014-05-28 15:57**MOT test number** 537388444134**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Pass with rectification** Offside Front Headlamp aim too low (1.8)



MOT #1	2013-10-28 14:39
MOT test number	966391703325
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
29 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-29
Last registration	2023-11-30
Complete history	See info



Registration #1	2010-10-29	25 mi
Registration #2	2013-10-28	42.252 mi
Registration #3	2014-05-28	49.711 mi
Registration #4	2015-05-13	54.551 mi
Registration #5	2016-05-18	59.518 mi
Registration #6	2017-05-17	63.317 mi
Registration #7	2018-05-17	67.782 mi
Registration #8	2018-10-31	68.495 mi
Registration #9	2019-05-29	70.277 mi
Registration #10	2019-05-29	70.277 mi
Registration #11	2019-05-29	70.277 mi
Registration #12	2019-05-29	70.277 mi
Registration #13	2019-05-29	70.277 mi
Registration #14	2019-05-29	70.277 mi
Registration #15	2019-05-29	70.277 mi
Registration #16	2019-05-29	70.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2775 mm
Kerb weight	1571 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles

2

Engine number

884841