




General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS EGS PICASSO
Colour	Brown
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-05
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-05
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	48
Total items failed	22

MOT #19	2023-06-16 13:09
MOT test number	951808830756
Result	✓ Passed
Next expiry date	2024-07-05
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #18	2023-06-15 20:41
MOT test number	688944061776
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Fail	Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #172022-06-17 12:24

MOT test number359239544497

Result		✓ Passed
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))	
Minor	Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

**MOT #16**

2022-06-14 16:10

MOT test number

188393743545

Result**✗ Failed**

- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Minor** Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #15

2021-07-06 12:56

MOT test number

814033462874

Result**✓ Passed**

- Advice** Front and rear brake discs corroded, pitted, worn and juddering-front and rear brake pads worn low-wishbone bushes perished-n/s/f ball joint has slight play-rear brakes slightly binding

**MOT #14**

2019-08-23 10:38

MOT test number

803666620421

Result

✓ Passed

Advice Front Brake disc worn, but not excessively both n/s and o/s inner faces (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin both n/s and o/s (1.1.13 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin both n/s and o/s (1.1.13 (a) (ii))**MOT #13**

2019-08-16 11:43

MOT test number

994604012520

Result

✗ Failed

Advice Front Brake disc worn, but not excessively both n/s and o/s inner faces (1.1.14 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin both n/s and o/s (1.1.13 (a) (ii))**Fail** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Exhaust system insecure rear exhaust bracket (6.1.2 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Brake pad(s) wearing thin both n/s and o/s (1.1.13 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #12**

2018-06-22 16:05

MOT test number

363209785104

Result

✓ Passed

**MOT #11** 2017-06-24 09:12**MOT test number** 844918321312**Result** ✓ Passed**Advice** Engine under tray fitted obscuring some components**MOT #10** 2016-06-28 14:04**MOT test number** 405185088267**Result** ✓ Passed**Advice** Offside front tyre has a cut across the tread which is not deep enough to reach the ply or cords**Advice** Offside Rear Nail in tyre**Advice** Offside front tyre is slightly worn on the edges of the tread**Advice** Under trays fitted obscuring inspection of some components**MOT #9** 2016-06-27 09:18**MOT test number** 145925832180**Result** ✗ Failed**Advice** Offside front tyre has a cut across the tread which is not deep enough to reach the ply or cords**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Rear Nail in tyre**Advice** Offside front tyre is slightly worn on the edges of the tread**Advice** Under trays fitted obscuring inspection of some components**Fail** Fuel system component leaking injector (7.2.3)**MOT #8** 2015-06-27 11:24**MOT test number** 739748575117**Result** ✓ Passed

**MOT #7** 2014-09-24 10:54**MOT test number** 698517664268**Result** Passed**MOT #6** 2014-09-23 08:16**MOT test number** 818366664255**Result** Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #5** 2014-07-20 12:21**MOT test number** 318851704463**Result** Passed**Notice** Front wipers slight smear**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Notice** Boot full not allowing full inspection of rear rear seats and belts**MOT #4** 2014-07-20 11:03**MOT test number** 786521704279**Result** Failed**Notice** Boot full not allowing full inspection of rear rear seats and belts**Notice** Front wipers slight smear**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #3** 2013-07-08 15:06**MOT test number** 186209783145**Result** ✓ Passed**MOT #2** 2013-07-05 12:25**MOT test number** 238366983187**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-11-20 12:09**MOT test number** 776765222372**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-28
Current registration	 *****
Plate since	2023-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-12-29
Last registration	2023-06-16
Complete history	See info



Registration #1	2009-12-29	10 mi
Registration #2	2012-11-20	22.853 mi
Registration #3	2013-07-05	25.544 mi
Registration #4	2013-07-08	25.544 mi
Registration #5	2014-07-20	40.453 mi
Registration #6	2014-07-20	40.453 mi
Registration #7	2014-09-23	42.162 mi
Registration #8	2014-09-24	42.162 mi
Registration #9	2015-06-27	45.823 mi
Registration #10	2016-06-27	50.111 mi
Registration #11	2016-06-28	50.114 mi
Registration #12	2016-06-29	50.117 mi
Registration #13	2016-06-30	50.120 mi
Registration #14	2016-07-01	50.123 mi
Registration #15	2016-07-02	50.126 mi
Registration #16	2016-07-03	50.129 mi
Registration #17	2016-07-04	50.132 mi
Registration #18	2016-07-05	50.135 mi
Registration #19	2016-07-06	50.138 mi
Registration #20	2016-07-07	50.141 mi
Registration #21	2016-07-08	50.144 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1680 mm
Length	4470 mm
Wheel base	2728 mm
Kerb weight	1499 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBN0169964