



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R AWD
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-31
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	42
Total items failed	16

MOT #18	2023-11-09 14:36
MOT test number	219995179633
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Offside Seat belt anchorage prescribed area is corroded but not considered excessive inner sills (7.1.1 (a) (i))
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Nearside Seat belt anchorage prescribed area is corroded but not considered excessive inner sills (7.1.1 (a) (i))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #17	2023-11-01 10:09
MOT test number	779382200554
Result	✗ Failed
Advice	Offside Seat belt anchorage prescribed area is corroded but not considered excessive inner sills (7.1.1 (a) (i))
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Nearside Seat belt anchorage prescribed area is corroded but not considered excessive inner sills (7.1.1 (a) (i))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #16**

2022-11-04 09:13

MOT test number

855550014609

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #15

2022-10-26 13:05

MOT test number

766324276931

Result

✗ Failed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #14** 2021-09-20 10:15**MOT test number** 555394063549**Result** ✓ Passed**MOT #13** 2021-09-11 10:57**MOT test number** 970768219850**Result** ✗ Failed**Fail** Central Rear Seat belt missing (7.1.2 (a))**MOT #12** 2021-02-17 10:22**MOT test number** 598391474970**Result** ✓ Passed**MOT #11** 2020-02-12 15:46**MOT test number** 622352789897**Result** ✓ Passed**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2020-02-12 11:19**MOT test number** 790967770341**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))**MOT #9** 2019-02-18 10:27**MOT test number** 331426212169**Result** ✓ Passed**Advice** Rear brakes slightly binding**Advice** Engine covers and or under trays fitted preventing a full inspection

**MOT #8**

2019-02-16 11:13

MOT test number

259460045649

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Rear brakes slightly binding**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Engine covers and or under trays fitted preventing a full inspection**MOT #7**

2018-02-09 15:32

MOT test number

291795625440

Result**✓ Passed****Advice** Rear Trailing arm has slight play in a pin/bush Both rear front bushes (2.4.G.2)**Advice** Engine covers and undertrays fitted preventing a full inspection**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Fuel Pipe/s corroded

**MOT #6** 2018-02-09 09:57**MOT test number** 479220612876**Result** ✗ Failed**Advice** Fuel Pipe/s corroded**Advice** Tyre worn close to the legal limit Both rear on limit (4.1.E.1)**Fail** Stop lamp remains on when the brakes are released (1.2.1e)**Advice** Engine covers and undertrays fitted preventing a full inspection**Advice** Rear Trailing arm has slight play in a pin/bush Both rear front bushes (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Electronic stability system warning lamp indicates a fault Traction control light illuminates when brake pedal depressed (3.4.1c)**MOT #5** 2017-02-09 09:01**MOT test number** 796980083165**Result** ✓ Passed**Advice** Engine covers and under trays fitted preventing a full inspection**MOT #4** 2016-02-05 15:04**MOT test number** 718367400037**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Engine Covers and Undertray's fitted preventing a full inspection

**MOT #3** 2016-02-03 09:04**MOT test number** 269970281231**Result** ✗ Failed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Rear Seat belt has a cut which has significantly weakened the webbing (5.2.2a)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Engine Covers and Undertray's fitted preventing a full inspection**MOT #2** 2015-02-17 16:27**MOT test number** 565718545084**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2015-02-17 16:27**MOT test number** 808958045007**Result** ✗ Failed**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-12-02
Last registration	2023-11-09
Complete history	See info



Registration #1	2011-12-02	29 mi
Registration #2	2015-02-17	30.044 mi
Registration #3	2016-02-03	38.423 mi
Registration #4	2016-02-05	38.473 mi
Registration #5	2017-02-09	47.558 mi
Registration #6	2018-02-09	56.176 mi
Registration #7	2018-02-09	56.178 mi
Registration #8	2019-02-16	64.007 mi
Registration #9	2019-02-18	64.009 mi
Registration #10	2020-02-12	71.493 mi
Registration #11	2020-02-12	71.493 mi
Registration #12	2020-02-12	71.493 mi
Registration #13	2020-02-12	71.493 mi
Registration #14	2020-02-12	71.493 mi
Registration #15	2020-02-12	71.493 mi
Registration #16	2020-02-12	71.493 mi
Registration #17	2020-02-12	71.493 mi
Registration #18	2020-02-12	71.493 mi
Registration #19	2020-02-12	71.493 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4365 mm
Wheel base	2560 mm
Kerb weight	1650 kg
Max. allowed weight	2190 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

2AD0355304