



CVIIRZC

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-09-08
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	18
Total items failed	10

MOT #13	2023-09-09 11:35
MOT test number	469655735855
Result	✓ Passed
Next expiry date	2024-09-08
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #12	2023-09-09 11:35
MOT test number	976085718582
Result	✗ Failed
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Pass with rectification	Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #11	2022-02-25 12:20
MOT test number	224959732856
Result	✓ Passed

**MOT #10** 2021-02-08 17:10**MOT test number** 262069515558**Result** ✓ Passed**MOT #9** 2019-03-12 11:42**MOT test number** 919834772547**Result** ✓ Passed**MOT #8** 2019-03-07 14:08**MOT test number** 938621903384**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**MOT #7** 2018-03-26 10:52**MOT test number** 254304192396**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2018-03-26 10:52**MOT test number** 191028463222**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Direction indicator not working (1.4.A.2c)**MOT #5** 2017-03-07 09:22**MOT test number** 879088438489**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (3.5.1i)**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front inner (3.5.1i)**MOT #4** 2016-03-23 09:26**MOT test number** 592290618125**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin inner (3.5.1g)**MOT #3** 2015-03-09 09:36**MOT test number** 779158065060**Result** ✓ Passed**Notice** Traction controll light on

**MOT #2** 2015-03-09 09:36**MOT test number** 757318265071**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Traction controll light on**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #1** 2014-03-10 14:41**MOT test number** 738969064082**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
8 September 2024

Tax status		Valid until 1 August
Days left		93
MOT expiry date		8 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	CV11RZC
Plate since	2024-03-29
Current registration	CV11RZC
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-29
Last registration	2023-09-09
Complete history	See info



Registration #1	2011-03-29	22 mi
Registration #2	2014-03-10	34.967 mi
Registration #3	2015-03-09	52.042 mi
Registration #4	2016-03-23	71.405 mi
Registration #5	2017-03-07	81.898 mi
Registration #6	2018-03-26	102.928 mi
Registration #7	2018-03-26	102.928 mi
Registration #8	2019-03-29	102.928 mi
Registration #9	2019-03-29	102.928 mi
Registration #10	2019-03-29	102.928 mi
Registration #11	2019-03-29	102.928 mi
Registration #12	2019-03-29	102.928 mi
Registration #13	2023-09-09	102.928 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AA82133