



NVHIFYX

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EVO GP
Colour	Red
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-05
Pictures	37
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-28
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	42
Total items failed	5

MOT #12	2023-06-29 13:02
---------	------------------

MOT test number	662349589802
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-28
------------------	------------

- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Suspension components
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2023-06-07 09:43

MOT test number

845891722710

Result**✗ Failed**

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing strong on inner edge
Recommend replacement (5.2.3 (e))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule Nearside + Offside (1.1.12 (f) (i))
- Advice** Front Shock absorbers has light misting of oil Nearside + Offside (5.3.2 (b))
- Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Nearside + Offside Rear Axle lower coil spring mounting (5.3.6 (a) (i))
- Minor** Offside Front Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Front Suspension components + sub frame corroded
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases Exhaust pipe connection (6.1.2 (a))

**MOT #10**

2022-06-07 13:21

MOT test number

666538073721

Result

✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge Nearside + Offside (5.2.3 (e))
- Minor** Offside Front Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Oil leak
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive Axle mounts (5.3.6 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Coil spring corroded Nearside + Offside (5.3.1 (b) (i))

MOT #9

2022-06-07 12:18

MOT test number

880795227963

Result

✗ Failed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Nearside Front Electrical wiring connectors for braking disconnected damaged (4.11 (a) (iii))
- Advice** Rear Coil spring corroded Nearside + Offside (5.3.1 (b) (i))
- Advice** Oil leak
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge Nearside + Offside (5.2.3 (e))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive Axle mounts (5.3.6 (a) (i))

**MOT #8** 2021-06-01 09:55**MOT test number** 730427523984**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #7** 2020-06-09 09:18**MOT test number** 931825635712**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #6** 2019-05-25 10:26**MOT test number** 964121314263**Result** ✓ Passed**MOT #5** 2018-06-01 11:34**MOT test number** 769678545870**Result** ✓ Passed**MOT #4** 2017-05-30 10:36**MOT test number** 780373670238**Result** ✓ Passed**MOT #3** 2016-06-01 08:33**MOT test number** 295968010840**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)



MOT #2	2015-06-03 15:31
MOT test number	845464055139
Result	✓ Passed

MOT #1	2014-06-11 13:43
MOT test number	885062764116
Result	✓ Passed

- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front brake wear indicator wiring chaffing on anti roll bar links.
- Notice** Items removed from driver's view prior to test



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
28 June 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-13
Last registration	2023-06-29
Complete history	See info



Registration #1	2011-06-13	23 mi
Registration #2	2014-06-11	12.877 mi
Registration #3	2015-06-03	17.555 mi
Registration #4	2016-06-01	25.002 mi
Registration #5	2017-05-30	35.333 mi
Registration #6	2018-06-01	46.458 mi
Registration #7	2019-05-25	57.611 mi
Registration #8	2020-05-29	68.777 mi
Registration #9	2021-05-29	79.944 mi
Registration #10	2022-05-29	91.111 mi
Registration #11	2023-05-29	102.278 mi
Registration #12	2024-05-29	113.445 mi
Registration #13	2025-05-29	124.612 mi
Registration #14	2026-05-29	135.779 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6332630