



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Grey
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-12-11
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-14
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	20
Total items failed	16

MOT #20 2023-12-08 14:57

MOT test number 951363783975

Result ✓ Passed

Next expiry date 2024-12-14

- Advice** Headlamp lenses discoloured
- Advice** N/s/f tyre wearing low
- Advice** Steel spare wheel fitted to o/s/f
- Advice** Sill panels corroding

MOT #19 2022-12-15 14:07

MOT test number 931489387945

Result ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear brake hoses perishing
- Advice** Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))

**MOT #18**

2022-12-07 14:48

MOT test number

559148849696

Result

✗ Failed

Fail Emissions not tested (8.2.2.2 (e))**Advice** Rear brake hoses perishing**Fail** Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))**Advice** Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))**Fail** Seat belt anchorage prescribed area strength or continuity significantly reduced o/s outer sill panel (7.1.1 (a) (i))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Seat belt anchorage prescribed area strength or continuity significantly reduced n/s outer sill panel (7.1.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Exhaust system insecure (6.1.2 (a))**MOT #17**

2021-12-09 14:22

MOT test number

764139966272

Result

✓ Passed

Advice Rear Exhaust mounting defective (6.1.2 (a))**MOT #16**

2020-06-03 10:00

MOT test number

612756557846

Result

✓ Passed

MOT #15

2019-06-04 15:23

MOT test number

841469279455

Result

✓ Passed

**MOT #14** 2019-05-31 11:13**MOT test number** 391626622612**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #13** 2018-05-21 10:52**MOT test number** 766688841149**Result** ✓ Passed**Advice** Rear tyres badly perished**Advice** Front tyres badly perished**MOT #12** 2018-05-21 10:52**MOT test number** 869665162083**Result** ✗ Failed**Advice** Rear tyres badly perished**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front tyres badly perished**MOT #11** 2017-04-26 09:52**MOT test number** 506236057255**Result** ✓ Passed**MOT #10** 2016-03-21 13:06**MOT test number** 894724640253**Result** ✓ Passed**Advice** Under trays fitted

**MOT #9** 2015-03-16 16:11**MOT test number** 608545875046**Result** ✓ Passed**MOT #8** 2015-03-16 13:22**MOT test number** 166905975451**Result** ✗ Failed**Fail** Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-01-29 14:19**MOT test number** 626179824023**Result** ✓ Passed**MOT #6** 2013-05-15 10:03**MOT test number** 647285333133**Result** ✓ Passed**MOT #5** 2012-05-15 15:51**MOT test number** 276866532447**Result** ✓ Passed

**MOT #4** 2012-04-04 13:17**MOT test number** 999535892090**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Notice** Rear tyre outer walls cracked**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #3** 2011-04-23 08:35**MOT test number** 397282411120**Result** ✓ Passed**MOT #2** 2010-06-24 11:35**MOT test number** 170955970199**Result** ✓ Passed**MOT #1** 2010-06-24 11:35**MOT test number** 470295970193**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 December 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-21
Last registration	2023-12-08
Complete history	See info



Registration #1	2007-06-21	22 mi
Registration #2	2010-06-24	16.834 mi
Registration #3	2011-04-23	21.241 mi
Registration #4	2012-04-04	35.025 mi
Registration #5	2012-05-15	36.894 mi
Registration #6	2013-05-15	49.349 mi
Registration #7	2014-01-29	57.338 mi
Registration #8	2015-03-16	69.001 mi
Registration #9	2015-03-16	69.001 mi
Registration #10	2016-03-21	77.553 mi
Registration #11	2017-04-26	78.934 mi
Registration #12	2018-05-29	80.315 mi
Registration #13	2019-06-28	81.696 mi
Registration #14	2020-07-27	83.077 mi
Registration #15	2021-08-26	84.458 mi
Registration #16	2022-09-25	85.839 mi
Registration #17	2023-10-24	87.220 mi
Registration #18	2024-11-23	88.601 mi
Registration #19	2025-12-22	90.000 mi
Registration #20	2026-01-21	91.400 mi
Registration #21	2027-02-20	92.800 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB660199901