





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT S TDI BLUEMOTION TECHNOLOGY
Colour	Silver
Year of manufacture	2015
Top speed	127 mph
0 - 100 km/h	11.0 seconds
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 kW / 120 HP / 118 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.3 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

		1
ᆮ	HLIV	-

LIICI Y I	
Date	2021-08-14
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-02
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #8	2023-10-25 15:07
MOT test number	254635770744
Result	✓ Passed
Next expiry date	2024-11-02

MOT #7		2023-10-23 12:04
MOT test	number	792015456122
Result		X Failed
Fail O	offside Headlamp levelling device inoperative (4.1.5 (a))	
Fail O	offside Headlamp aim too high adjusters not working (4.1.2 (a))	

MOT #6		2022-11-03 12:20
MOT test	number	934880115429
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front tyre tread worn to 3mm	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front tyre tread worn to 3mm	
Advice	All rear seating in folded position during test - load area full-unable to test rear	seat belts

CarCheck.co.uk page 3/11



MOT #5 2021-09-22 13:06

MOT test number 626121908317

MOT #4 2020-11-11 15:24

MOT test number 357339912279

Result ✓ Passed

MOT #3 2019-05-03 08:44

MOT test number 750425273869

Result
✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #2 2019-05-03 08:44

MOT test number 984126031185

Result X Failed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #1 2018-05-21 09:33

MOT test number 397300705114

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date


Category

Type

Damage 2

Date

Type Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIN
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-23
Last registration	2023-10-25
Complete history	See info



Registration #1	2015-05-23	7 mi
Registration #2	2018-05-21	68.663 mi
Registration #3	2019-05-03	91.189 mi
Registration #4	2019-05-03	91.189 mi
Registration #5	2020-11-11	104.657 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		111.7777 est
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1516 mm
Length	4771 mm
Wheel base	2712 mm
Kerb weight	1400 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	59 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	pago 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	DCXA009039