



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TAKUYA
Colour	Blue
Year of manufacture	2012
Top speed	134 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	193 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-02-12
Pictures	21
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-10
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	26
Total items failed	17

MOT #16	2024-02-13 15:49
MOT test number	142979615765
Result	✓ Passed
Next expiry date	2025-03-10
Advice	Fuel cap securing strap broken
Advice	Both the rear tyres worn to 4mm and slightly perished through tread (the legal limit is 1.6mm
Advice	Both front headlamp covers slightly deteriorated
Advice	Various underbody and component corrosion

**MOT #15**

2024-02-12 10:29

**MOT test number**

823579372435

**Result****✗ Failed**

- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Both front headlamp covers slightly deteriorated
- Advice** Various underbody and component corrosion
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Fuel cap securing strap broken
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Both the rear tyres worn to 4mm and slightly perished through tread (the legal limit is 1.6mm)

**MOT #14**

2023-03-02 10:02

**MOT test number**

330610811847

**Result**

✓ Passed

- Advice** Fuel cap securing strap broken
- Advice** All brake pads 60% worn , all brake discs slightly lipped
- Advice** Various underbody and component corrosion
- Advice** Both front headlamp covers slightly deteriorated
- Advice** O/s/r tyre worn to 4mm, both rear tyres slightly perished through tread (the legal limit is 1.6mm)

**MOT #13**

2022-03-11 17:26

**MOT test number**

708820522077

**Result**

✓ Passed

- Advice** Complete under body cover panels fitted concealing some testable components.
- Advice** CARRIED OUT VEHICLE INSPECTION UNDER WET CONDITIONS.
- Advice** Engine cover & under body cover panels fitted obscuring some testable components.
- Advice** Sill cover body panel covers fitted preventing full inspection of some testable items.

**MOT #12**

2022-01-11 11:00

**MOT test number**

993397062714

**Result**

✓ Passed

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**MOT #11**

2021-01-08 12:56

**MOT test number**

432170880205

**Result**

✓ Passed

**MOT #10**

2021-01-08 09:29

**MOT test number**

767485554371

**Result**

✗ Failed

**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Advice** Rear exhaust heat shield insecure**MOT #9**

2020-01-10 09:37

**MOT test number**

308250527961

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MOT #8**

2020-01-10 09:37

**MOT test number**

192202678269

**Result**

✗ Failed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**MOT #7**

2018-12-29 08:33

**MOT test number**

662226867566

**Result**

✓ Passed

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #6** 2018-12-28 11:42**MOT test number** 150182841260**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2018-01-05 12:31**MOT test number** 810301771585**Result** ✓ Passed**MOT #4** 2018-01-05 09:45**MOT test number** 275455747563**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2017-01-09 09:48**MOT test number** 349552799883**Result** ✓ Passed**MOT #2** 2016-01-11 10:46**MOT test number** 275201372100**Result** ✓ Passed**MOT #1** 2015-03-24 10:03**MOT test number** 578743585015**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
10 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	10 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-






Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-03-17
Last registration	2024-02-13
Complete history	<a href="#">See info</a>



Registration #1	2012-03-17	13 mi
Registration #2	2015-03-24	10.343 mi
Registration #3	2016-01-11	13.178 mi
Registration #4	2017-01-09	23.795 mi
Registration #5	2018-01-05	34.046 mi
Registration #6	2018-01-05	34.046 mi
Registration #7	2018-12-28	44.410 mi
Registration #8	2018-12-29	44.412 mi
Registration #9	2020-01-10	54.325 mi
Registration #10	2020-01-10	54.325 mi
Registration #11	2020-01-10	54.325 mi
Registration #12	2020-01-10	54.325 mi
Registration #13	2020-01-10	54.325 mi
Registration #14	2020-01-10	54.325 mi
Registration #15	2020-01-10	54.325 mi
Registration #16	2020-01-10	54.325 mi
Registration #17	2020-01-10	54.325 mi
Registration #18	2020-01-10	54.325 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1435 kg
Max. allowed weight	1955 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 20409679