



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI DSG
Colour	Grey
Year of manufacture	2009
Top speed	128 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G





## MOT history

MOT expiry date	2022-05-06
-----------------	------------

MOT pass rate	76 %
---------------	------

MOT passed	13
------------	----

Failed MOT tests	4
------------------	---

Total advice items	21
--------------------	----

Total items failed	13
--------------------	----

MOT #17	2021-05-07 17:00
---------	------------------

MOT test number	691732050533
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2022-05-06
------------------	------------

Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))
--------	--

Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	---

Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
--------	--

MOT #16	2021-05-07 15:54
---------	------------------

MOT test number	951251171934
-----------------	--------------

Result	✗ Failed
--------	----------

Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))
--------	--

Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
------	---

Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
--------	--

Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
------	---

Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	---

Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
------	--

Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
------	---

**MOT #15**

2019-08-03 17:26

**MOT test number**

640008591740

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn unevenly (twisted).**MOT #14**

2019-08-03 17:26

**MOT test number**

411299056641

**Result**

✗ Failed

**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Tyre worn unevenly (twisted).**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13**

2018-07-21 12:59

**MOT test number**

704377896296

**Result**

✓ Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**Advice** Under tray fitted.**MOT #12**

2018-07-21 12:59

**MOT test number**

910075351867

**Result**

✗ Failed

**Advice** Under tray fitted.**Pass with rectification** Offside Front Direction indicator not working (4.4.1 (a) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))



**MOT #11** 2017-06-19 16:24**MOT test number** 208623409606**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #10** 2016-12-31 13:58**MOT test number** 601704788904**Result** ✓ Passed**MOT #9** 2016-11-17 09:08**MOT test number** 620164979567**Result** ✓ Passed**MOT #8** 2016-11-16 15:43**MOT test number** 709468144119**Result** ✗ Failed

- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Direction indicator not working (1.4.A.2c)
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Headlamp aim too high (1.8)



<b>MOT #7</b>	2015-11-17 16:21
---------------	------------------

<b>MOT test number</b>	635049191640
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2015-06-27 16:24
---------------	------------------

<b>MOT test number</b>	187038675184
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2014-11-14 16:00
---------------	------------------

<b>MOT test number</b>	445398514317
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2014-05-19 14:04
---------------	------------------

<b>MOT test number</b>	835009434165
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2013-11-18 12:37
---------------	------------------

<b>MOT test number</b>	895602823366
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2013-05-22 16:28
---------------	------------------

<b>MOT test number</b>	968412143185
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #1</b>	2012-11-19 10:37
---------------	------------------

<b>MOT test number</b>	935244822373
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

×

Untaxed

Tax expired:  
1 December 2020

×

MOT

Expired:  
6 May 2022

Tax status

Expired at 1 December 2020

Days left

1244 days too late

MOT expiry date

6 May 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>AD09PXN</b>
Plate since	2024-03-29
Current registration	 <b>AD09PXN</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-07-25
Last registration	2021-05-07
Complete history	<a href="#">See info</a>



Registration #1	2009-07-25	19 mi
Registration #2	2012-11-19	4.813 mi
Registration #3	2013-05-22	11.095 mi
Registration #4	2013-11-18	16.174 mi
Registration #5	2014-05-19	19.999 mi
Registration #6	2014-11-14	23.625 mi
Registration #7	2015-06-27	35.231 mi
Registration #8	2015-11-17	38.078 mi
Registration #9	2016-11-16	40.837 mi
Registration #10	2016-11-16	40.837 mi
Registration #11	2016-11-16	40.837 mi
Registration #12	2016-11-16	40.837 mi
Registration #13	2016-11-16	40.837 mi
Registration #14	2016-11-16	40.837 mi
Registration #15	2016-11-16	40.837 mi
Registration #16	2016-11-16	40.837 mi
Registration #17	2016-11-16	40.837 mi
Registration #18	2016-11-16	40.837 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1476 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 192068