





report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Grey
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-11-05

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-11-24
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	15
Total items failed	8

MOT #21	2023-11-14 11:15
MOT test number	220471595975
Result	✓ Passed
Next expiry date	2024-11-24

MOT #20	2022-11-23 15:40
MOT test number	871371560927
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge low (5.2.3 (e))	e inner and outer edge of tread area worn
Advice Offside Rear Tyre slightly damaged/cracking or perishing	g (5.2.3 (d) (ii))

MOT #19	2022-11-22 12:43
MOT test number	297633812191
Result	★ Failed
Advice Offside Front Tyre worn close to le low (5.2.3 (e))	gal limit/worn on edge inner and outer edge of tread area worn
Fail Nearside Rear Tyre has a cut in exces (5.2.3 (d) (i))	s of the requirements deep enough to reach the ply or cords
Advice Offside Rear Tyre slightly damaged	d/cracking or perishing (5.2.3 (d) (ii))

MOT #18	2021-11-25 15:04
MOT test number	100851413638
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number

Result

Nearside Front Headlamp aim too low (4.1.2 (a))

Fail
Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #16 2021-04-08 11:14

MOT test number 430094475750

Result ✓ Passed

MOT #15

MOT test number

862995453441

Result

Fail Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Emissions not tested (8.2.1.2 (d))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #14
 2020-03-30 11:18

 MOT test number
 213054833962

 Result
 ✓ Passed

 MOT #13
 2020-03-30 10:28

 MOT test number
 571751473286

 Result
 X Failed

 Fail
 Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12 2019-04-09 08:11

MOT test number 635977408421

MOT #11 2018-04-16 10:40

MOT test number 944846943694

Result

Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Rear Tyre worn close to the legal limit 2.5mm also perishing/cracking and has nail in tread 195/60/15 (4.1.E.1)

Advice Offside front tyre perished/cracking 195/60/15

MOT #10 2018-04-16 10:40

MOT test number 978837022158

Result X Failed

Advice Offside front tyre perished/cracking 195/60/15

Pass with rectification Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Offside Rear Tyre worn close to the legal limit 2.5mm also perishing/cracking and has nail in tread 195/60/15 (4.1.E.1)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #9 2017-04-18 10:37

MOT test number 851689646674

Result

Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8 2017-04-18 10:37

MOT test number 670434734628

Result X Failed

Pass with rectification Nearside Rear Registration plate lamp not working replaced bulb Ilb239

(1.1.C.1d) **Advice**

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2016-04-18 13:16

MOT test number 205836341817

Result \(\sqrt{Passed} \)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #6 2016-03-30 10:27

MOT test number 847606464528

Result
✓ Passed

MOT #5 2015-04-27 09:11

MOT test number 285797515478

Result ✓ Passed

MOT #4 2014-04-22 09:41

MOT test number 298952414185

Result ✓ Passed

MOT #3 2013-04-04 10:29

MOT test number 137604693098

Result ✓ Passed

MOT #2 2012-04-03 10:07

MOT test number 187044192466

Result

Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #1 2011-04-12 09:27

MOT test number 395632001162

Result ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check





Expires: 24 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NE ZIN
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-04-26
Last registration	2023-11-14
Complete history	See info



Registration #1	2008-04-26	29 mi
Registration #2	2011-04-12	17.716 mi
Registration #3	2012-04-03	22.403 mi
Registration #4	2013-04-04	27.101 mi
Registration #5	2014-04-22	32.785 mi
Registration #6	2015-04-27	39.161 mi
Registration #7	2016-03-30	43.597 mi
Registration #8	2016-04-18	43.612 mi
Registration #9	2017-04-18	55.340 mi
Registration #10	2017-04-18	55.340 mi
Registration #11	2018-04-16	65.417 mi
Registration #12	2018-04-16	65.417 mi
Registration #12	2010-04-10	05.417 1111
Registration #13	2010-04-10	03.417 Hil
-		03.417 Hill
Registration #13		03.417 1111
Registration #13 Registration #14		03.417 1111
Registration #13 Registration #14 Registration #15		03.417 1111
Registration #13 Registration #14 Registration #15 Registration #16		03.417 1111
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		03.417 1111
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		03.417 1111
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		03.417 1111
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

Engine number 8A48618