





report date: 2024-03-29

#### General information

| Make                | KIA             |
|---------------------|-----------------|
| Model               | RIO GT-LINE ISG |
| Colour              | Grey            |
| Year of manufacture | 2018            |
| Top speed           | 118 mph         |
| 0 - 60 mph          | 9.8 seconds     |
| Gearbox             | 6 speed Manual  |

### Engine & fuel consumption

| Power                   | 118 BHP             |
|-------------------------|---------------------|
| Max. torque             | 172 Nm at 4.000 rpm |
| Engine capacity         | 998 сс              |
| Cylinders               | 3                   |
| Fuel type               | Petrol              |
| Consumption city        | 46.3 mpg            |
| Consumption extra urban | 62.8 mpg            |
| Consumption combined    | 47.1 mpg            |
| CO2 emission            | 117 g/km            |
| CO2 label               | С                   |



CarCheck.co.uk page 1/11



## Internet history

#### Entry 2

Date 2022-01-24

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

| Date          | 2022-01-11         |  |
|---------------|--------------------|--|
| Pictures      | 1                  |  |
| Listing price | <u>View report</u> |  |



source: cargurus.co.uk

CarCheck.co.uk page 2/11



# MOT history

| MOT expiry date    | 2024-08-14 |
|--------------------|------------|
| MOT pass rate      | 75 %       |
| MOT passed         | 3          |
| Failed MOT tests   | 1          |
| Total advice items | 6          |
| Total items failed | 1          |

| MOT #4    |  | 2023-08-14 15:08 |
|-----------|--|------------------|
| MOT test  | number   | 164498453824     |
| Result    |  | ✓ Passed         |
| Next expi | ry date  | 2024-08-14       |
| Advice    | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice    | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice    | Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))           |                  |

| MOT #3  |   | 2023-08-14 13:14 |
|---|---|------------------|
| MOT test  | number  | 481742172314     |
| Result  |   | 🗙 Failed         |
| Advice  | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                 |                  |
| Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))           |   |                  |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |   |                  |
| Fail O  | ffside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii) | )                |

| MOT #2          | 2022-08-15 15:26 |
|-----------------|------------------|
| MOT test number | 516532382823     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/11



MOT #1 2021-11-16 15:26

MOT test number 197594261910

CarCheck.co.uk page 4/11



## Tax & MOT check



| Tax status       | Valid until 1 September |
|------------------|-------------------------|
| Days left        | 125                     |
| MOT expiry date  | 14 August 2024          |
| Full MOT history | See MOT history         |

#### Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | G          |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

| For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have?  Check it in the premium report and see all owner registrations. Download the full report here.  More Info >  Plate changes  See in this check if this KIA had different number plates. |  |                  |
|--|--|------------------|
| Plate changes  See in this check if this KIA had different number plates.  |  |                  |
| Plate changes  See in this check if this KIA had different number plates.  |  |                  |
| Plate changes  See in this check if this KIA had different number plates.  | HARMAN CO. C.  |                  |
| Plate changes  See in this check if this KIA had different number plates.  |  |                  |
| Plate changes  See in this check if this KIA had different number plates.  | ***************************************  |                  |
| Plate changes  See in this check if this KIA had different number plates.  |  |                  |
| Plate changes  See in this check if this KIA had different number plates.  | manage of the same |                  |
| Plate changes  See in this check if this KIA had different number plates.  | ***************************************  |                  |
| Plate changes  See in this check if this KIA had different number plates.  | ***************************************  |                  |
| Plate changes  See in this check if this KIA had different number plates.  |  |                  |
| See in this check if this KIA had different number plates.   |  | More info >      |
| See in this check if this KIA had different number plates.   |  |                  |
| 狀<br>UK  | Plate changes  |                  |
| 狀<br>UK  |  |                  |
| NE VIK   | See in this check if this kid had different number plates.   |                  |
| NE VIK   |  |                  |
| NE VIK   | Number of plates   | ,                |
| NE VIK   |  |                  |
| Platte since   | Current registration   | IK SIES          |
| Platte since   | Plate since  |                  |
| Platte since   |  |                  |
| More info  | Current registration   | NIZ<br>AIS<br>UK |
| More info  | Finite since   |                  |
| More info  |  |                  |
|  |  | More info >      |

CarCheck.co.uk page 8/11



#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info >

CarCheck.co.uk page 9/11



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 7          |
| First mileage registration | 2018-11-30 |
| Last registration          | 2023-08-14 |
| Complete history           | See info   |



| Registration #1 | 2018-11-30 | 28 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2021-11-16 | 13.120 mi |
| Registration #3 |            | 11.777 es |
| Registration #4 |            | 11.777 es |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 11.117 es |
| Registration #7 |            | 11.177 es |

More info >

CarCheck.co.uk page 10/11



## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| 50501 |                  |
| 50566 |                  |
| 50567 |                  |
| 50569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 93%             |
| Children       | 84%             |
| Pedestrian     | 71%             |
| Safety systems | 59%             |
| Overall rating | 80%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1725 mm |
|---------------------|---------|
| Height              | 1450 mm |
| Length              | 4070 mm |
| Wheel base          | 2580 mm |
| Kerb weight         | 1165 kg |
| Max. allowed weight | 1610 kg |

# Additional information

| Fuel tank capacity                | 45 I             |       |
|-----------------------------------|------------------|-------|
| Fuel delivery                     | Direct Injection |       |
| Number of doors                   | 5                |       |
| Number of seats<br>CarCheck.co.uk | 5 page           | 11/11 |

Number of axles 2

**Engine number** G3LCJP076272