



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | NISSAN |
| Model | PIXO N-TEC |
| Colour | Silver |
| Year of manufacture | 2009 |
| Top speed | 96 mph |
| 0 - 60 mph | 14.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 67 BHP |
| Max. torque | 90 Nm at 3.400 rpm |
| Engine capacity | 996 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 103 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-05 |
| Pictures | 11 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-22 |
| MOT pass rate | 60 % |
| MOT passed | 12 |
| Failed MOT tests | 8 |
| Total advice items | 12 |
| Total items failed | 14 |

| | |
|------------------|------------------|
| MOT #20 | 2023-10-11 11:23 |
| MOT test number | 360588650049 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-22 |

| | |
|-------------------------|--|
| MOT #19 | 2023-10-11 11:23 |
| MOT test number | 255966648793 |
| Result | ✗ Failed |
| Pass with rectification | Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) |

| | |
|-----------------|--|
| MOT #18 | 2022-10-22 14:43 |
| MOT test number | 352178801885 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #17 | 2021-10-23 12:27 |
| MOT test number | 892130670367 |
| Result | ✓ Passed |
| Advice | Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) |

**MOT #16** 2021-10-23 10:13**MOT test number** 749363594497**Result** ✗ Failed**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #15** 2020-10-09 17:16**MOT test number** 372941338455**Result** ✓ Passed**MOT #14** 2020-10-09 17:16**MOT test number** 583715753783**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #13** 2019-11-13 12:22**MOT test number** 494035479801**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12** 2018-10-26 10:00**MOT test number** 851468488903**Result** ✓ Passed**MOT #11** 2018-10-26 10:00**MOT test number** 607326221023**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**MOT #10** 2017-10-02 11:29**MOT test number** 116083230699**Result** ✓ Passed

- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit slightly out of shape (4.1.E.1)

MOT #9 2017-09-29 11:22**MOT test number** 258593686985**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Nearside Front Tyre worn close to the legal limit slightly out of shape (4.1.E.1)

MOT #8 2016-09-30 15:05**MOT test number** 874853889037**Result** ✓ Passed**MOT #7** 2016-09-30 15:05**MOT test number** 807510076125**Result** ✗ Failed

- Pass with rectification** Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #6** 2015-09-09 11:30**MOT test number** 115798729298**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-09-09 12:32**MOT test number** 998872454224**Result** ✓ Passed**MOT #4** 2014-09-09 10:39**MOT test number** 186412054229**Result** ✗ Failed**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2013-09-05 17:16**MOT test number** 326978743229**Result** ✓ Passed**MOT #2** 2013-09-05 17:16**MOT test number** 369868543246**Result** ✗ Failed**Pass with rectification** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Obligatory mirror insecure (8.1.1)



| | |
|-----------------|------------------|
| MOT #1 | 2012-07-23 10:05 |
| MOT test number | 579275202292 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 22 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  ***** |
| Plate since | 2024-03-29 |
| Current registration |  ***** |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2009-07-31 |
| Last registration | 2023-10-11 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-07-31 | 24 mi |
| Registration #2 | 2012-07-23 | 32.880 mi |
| Registration #3 | 2013-09-05 | 39.759 mi |
| Registration #4 | 2014-09-09 | 48.569 mi |
| Registration #5 | 2014-09-09 | 48.576 mi |
| Registration #6 | 2015-09-09 | 57.705 mi |
| Registration #7 | 2016-09-30 | 69.831 mi |
| Registration #8 | 2016-09-30 | 69.831 mi |
| Registration #9 | 2017-09-29 | 78.924 mi |
| Registration #10 | 2017-10-02 | 79.059 mi |
| Registration #11 | 2018-10-26 | 80.005 mi |
| Registration #12 | 2019-10-26 | 80.005 mi |
| Registration #13 | 2019-10-26 | 80.005 mi |
| Registration #14 | 2019-10-26 | 80.005 mi |
| Registration #15 | 2019-10-26 | 80.005 mi |
| Registration #16 | 2019-10-26 | 80.005 mi |
| Registration #17 | 2019-10-26 | 80.005 mi |
| Registration #18 | 2019-10-26 | 80.005 mi |
| Registration #19 | 2019-10-26 | 80.005 mi |
| Registration #20 | 2019-10-26 | 80.005 mi |
| Registration #21 | 2019-10-26 | 80.005 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1630 mm |
| Height | 1470 mm |
| Length | 3565 mm |
| Wheel base | 2360 mm |
| Kerb weight | 855 kg |
| Max. allowed weight | 1250 kg |

Additional information

| | |
|-----------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 107462 |