





report date: 2024-03-29

#### General information

Make	AUDI
Model	A3 TFSI
Colour	Black
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	125 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/13



# Internet history

#### Entry 1

Date	2021-01-27
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-06
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	13
Total items failed	4

MOT #15	2024-02-06 13:14
MOT test number	764032724843
Result	✓ Passed
Next expiry date	2025-02-06

MOT #	14	2024-02-05 14:26
MOT te	est number	510270932247
Result		<b>X</b> Failed
<b>Fail</b> of dirt	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer (6.1.7 (g) (ii))	prevents the ingress
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #13	2023-02-04 10:16
MOT test number	865756497678
Result	<b>✓</b> Passed

MOT #12	2022-02-07 14:04
MOT test number	310474340509
Result	✓ Passed
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	

CarCheck.co.uk page 3/13



MOT #11 2021-01-20 11:38

**MOT test number** 101627720646

MOT #10 2019-05-16 08:19

**MOT test number** 677270985836

**Result** 
✓ Passed

Advice Tyre slightly damaged/cracking or perishing Nearside rear inner sidewall (5.2.3 (d) (ii))

MOT #9 2018-05-19 08:23

**MOT test number** 488697850153

Advice Nearside rear tyre has small spilt on inner sidewall

MOT #8 2017-05-17 12:31

MOT test number 758330781136

**Result** 
✓ Passed

MOT #7 2016-06-28 11:54

**MOT test number** 505770577926

Result \( \sqrt{Passed} \)

MOT #6 2015-04-13 09:48

MOT test number 427393405144

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/13



MOT #5 2015-04-13 09:48

MOT test number 107413405166

Result X Failed

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2014-04-11 16:24

**MOT test number** 897421404175

Result \square Passed

**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2013-03-28 16:37

**MOT test number** 608117083059

**Notice** Chips in screen

**Notice** Both front tyres cracking and starting to split

MOT #2 2013-03-28 11:36

**MOT test number** 488887683051

**Result** X Failed

**Notice** Chips in screen

**Notice** Rear pads getting low

Notice O/s/r tyre badly cracking, starting to split and getting low

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Notice** Both front tyres cracking and starting to split

Notice N/s/r tyre worn on inner edge, cracking, starting to split and getting low

CarCheck.co.uk page 5/13



MOT #1 2011-07-15 16:11

**MOT test number** 605456591164

**Result** ✓ Passed

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	6 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	
HARMAN CO.	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SIL
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-08-20
Last registration	2024-02-06
Complete history	See info



Registration #1	2008-08-20	17 mi
Registration #2	2011-07-15	20.126 mi
Registration #3	2013-03-28	37.379 mi
Registration #4	2013-03-28	37.379 mi
Registration #5	2014-04-11	43.019 mi
Registration #6	2015-04-13	50.314 mi
Registration #7	2016-06-28	56.359 mi
Registration #8	2017-05-17	62.301 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		0.074
Registration #16		71.777 es

More info >

page 12/13 CarCheck.co.uk



# Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4214 mm
Wheel base	2578 mm
Max. allowed weight	1820 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number Carcheck.co.uk	CAX 037991 page 13/13