



BN60ENP

report date: 2024-03-29

General information

Make	FIAT
Model	FIORINO 16V MULTIJET SX
Colour	Blue
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2023-05-08
Pictures	11
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-27
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-05-11
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	36
Total items failed	3

MOT #17 2023-05-12 14:41

MOT test number 142469485573

Result ✓ Passed

Next expiry date 2024-05-11

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive surface corrosion (5.3.6 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2023-05-11 14:15

MOT test number 224551299960

Result ✗ Failed**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive surface corrosion (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2022-09-29 10:33

MOT test number 113614615750

Result ✓ Passed

**MOT #14** 2021-10-06 15:47**MOT test number** 914383322166**Result** ✓ Passed**MOT #13** 2021-05-28 10:15**MOT test number** 773678582368**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm. Tyre wearing on edges. (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view chip in windscreen. (3.2 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2021-05-28 10:15**MOT test number** 441096459990**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm. Tyre wearing on edges. (5.2.3 (e))**Pass with rectification** Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Windscreen damaged but not adversely affecting driver's view chip in windscreen. (3.2 (a) (i))



MOT #11	2020-06-18 09:03
MOT test number	187124736281
Result	✓ Passed
Advice	Nearside Rear tyre perished / cracking

MOT #10	2020-06-17 11:52
MOT test number	236731921769
Result	✗ Failed
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm 185 65 15 (5.2.3 (e))
MAJOR	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice	Nearside Rear tyre perished / cracking
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Front Brake disc significantly and obviously worn corroded (1.1.14 (a) (i))
MAJOR	Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #9	2019-05-11 08:47
MOT test number	820299887511
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8	2018-05-11 15:58
MOT test number	417730799856
Result	✓ Passed

MOT #7	2018-05-11 13:46
MOT test number	268363119254
Result	✗ Failed
Fail	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #6** 2017-05-12 12:26**MOT test number** 469012842211**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2016-09-06 15:46**MOT test number** 218049375324**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)**MOT #4** 2015-09-25 07:41**MOT test number** 305137449248**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-09-12 15:15**MOT test number** 335615154263**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2014-09-12 09:01**MOT test number** 508465454289**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #1	2013-09-06 09:54
MOT test number	657879743266
Result	✓ Passed
<div>Notice Front brake pads worn low</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 May 2024

Tax status		Valid until 1 April
Days left		337
MOT expiry date		11 May 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-09-30
Last registration	2023-05-12
Complete history	See info



Registration #1	2010-09-30	29 mi
Registration #2	2013-09-06	39.406 mi
Registration #3	2014-09-12	16.144 mi
Registration #4	2014-09-12	161.444 mi
Registration #5	2015-09-25	62.971 mi
Registration #6	2016-09-06	69.953 mi
Registration #7	2017-05-12	73.031 mi
Registration #8	2018-05-11	79.011 mi
Registration #9	2018-05-11	79.011 mi
Registration #10	2019-05-11	86.625 mi
Registration #11	2019-05-11	86.625 mi
Registration #12	2019-05-11	86.625 mi
Registration #13	2019-05-11	86.625 mi
Registration #14	2019-05-11	86.625 mi
Registration #15	2019-05-11	86.625 mi
Registration #16	2019-05-11	86.625 mi
Registration #17	2019-05-11	86.625 mi
Registration #18	2019-05-11	86.625 mi
Registration #19	2019-05-11	86.625 mi
Registration #20	2019-05-11	86.625 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3632544