



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Silver
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-11-07
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-31
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	24
Total items failed	7

MOT #13	2024-02-01 12:28
---------	------------------

MOT test number	526979952208
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-31
------------------	------------

Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Engine covers and under trays fitted to the vehicle.
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2024-01-31 16:32

**MOT test number**

844089217362

**Result**

✗ Failed

**Fail**

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice**

Engine covers and under trays fitted to the vehicle.

**Fail**

Offside Headlamp aim too high (4.1.2 (a))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice**

Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Minor**

Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail**

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail**

Nearside Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

**Advice**

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice**

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2023-01-03 16:17

**MOT test number**

936882535320

**Result**

✓ Passed

**Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2022-01-24 14:17

**MOT test number**

355205309208

**Result**

✓ Passed

**MOT #9** 2021-12-03 11:47**MOT test number** 853670929274**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2021-06-28 10:07**MOT test number** 722002218697**Result** ✓ Passed**MOT #7** 2020-06-09 08:26**MOT test number** 875097894777**Result** ✓ Passed**MOT #6** 2019-06-04 10:05**MOT test number** 967088513296**Result** ✓ Passed**MOT #5** 2018-06-05 09:01**MOT test number** 981965702384**Result** ✓ Passed**MOT #4** 2017-06-06 09:17**MOT test number** 471364395589**Result** ✓ Passed



MOT #3	2016-06-13 10:30
MOT test number	133703079801
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit 3mm and has nail in tread (4.1.E.1)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2	2015-06-28 07:06
MOT test number	229369475412
Result	✓ Passed

MOT #1	2014-11-21 10:07
MOT test number	266755324309
Result	✓ Passed
Notice	Vehicle's internal headlight adjuster altered to recheck lights



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
31 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	31 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-11-30
Last registration	2024-02-01
Complete history	<a href="#">See info</a>



Registration #1	2011-11-30	8 mi
Registration #2	2014-11-21	16.092 mi
Registration #3	2015-06-28	17.719 mi
Registration #4	2016-06-13	23.784 mi
Registration #5	2017-06-06	30.126 mi
Registration #6	2018-06-05	35.474 mi
Registration #7	2019-06-04	41.001 mi
Registration #8	2020-06-09	45.066 mi
Registration #9	2021-06-09	50.000 mi
Registration #10	2022-06-09	55.000 mi
Registration #11	2023-06-09	60.000 mi
Registration #12	2024-06-09	65.000 mi
Registration #13	2025-06-09	70.000 mi
Registration #14	2026-06-09	75.000 mi
Registration #15	2027-06-09	80.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1860 mm
Height	1479 mm
Length	4289 mm
Wheel base	2750 mm
Kerb weight	1595 kg
Max. allowed weight	2238 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYYF4080887