



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI SE
Colour	Black
Year of manufacture	2016
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-04-12
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-14
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	5
Total items failed	19

MOT #9	2024-02-15 17:09
MOT test number	315329676040
Result	✓ Passed
Next expiry date	2025-02-14



MOT #8	2024-02-15 11:42
MOT test number	100460487284
Result	✗ Failed
Fail	Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Headlamp levelling device inoperative (4.1.5 (a))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Headlamp aim too high (4.1.2 (a))

MOT #7	2023-03-20 14:42
MOT test number	652052293693
Result	✓ Passed

**MOT #6** 2023-03-20 09:32**MOT test number** 797441473819**Result** ✗ Failed

- Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #5 2022-04-14 13:49**MOT test number** 823460570218**Result** ✓ Passed**MOT #4** 2021-08-04 11:25**MOT test number** 481060995369**Result** ✓ Passed

- Advice** Nearside Rear sliding door sticking slightly
- Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))
- Advice** Front pads wearing low

MOT #3 2020-07-30 15:26**MOT test number** 891648607559**Result** ✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #2	2020-07-27 15:51
MOT test number	627469263643
Result	✗ Failed
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #1	2019-07-20 10:55
MOT test number	755164950398
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
14 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-08-09
Last registration	2024-02-15
Complete history	See info



Registration #1	2016-08-09	9 mi
Registration #2	2019-07-20	50.576 mi
Registration #3	2020-07-27	58.941 mi
Registration #4	2020-07-30	58.943 mi
Registration #5	2021-08-04	63.603 mi
Registration #6	2022-08-04	63.603 mi
Registration #7	2022-08-04	63.603 mi
Registration #8	2022-08-04	63.603 mi
Registration #9	2022-08-04	63.603 mi
Registration #10	2022-08-04	63.603 mi
Registration #11	2022-08-04	63.603 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2248 kg
Max. allowed weight	3070 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBG021308