



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 T S S60
Colour	Red
Year of manufacture	2002
Top speed	130 mph
0 - 60 mph	9.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	240 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	37.7 mpg
Consumption combined	28.0 mpg
CO2 emission	236 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-09-08
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-07-28
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	99
Total items failed	22

MOT #21	2020-07-18 11:59
MOT test number	559907293638
Result	✓ Passed
Next expiry date	2021-07-28
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Slight play in nearside and offside front steering arms
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #20**

2020-07-11 09:23

MOT test number

511972753417

Result**✗ Failed**

- Advice** Slight play in nearside and offside front steering arms
- MAJOR** Rear Registration plate insecure (0.1 (a))
- MAJOR** Position lamp switch does not operate in accordance with the requirements (4.2.2 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- MAJOR** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))
- MAJOR** Emissions not tested oil level to low, [not reading on dipstick] (8.2.1.2 (d))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Dipswitch does not operate immediately when selected on main beam does not keep main beam on (4.1.3 (b))
- MAJOR** Rear fog lamp switch inoperative (4.5.3 (a) (ii))

MOT #19

2019-07-13 11:11

MOT test number

606515902709

Result**✓ Passed**

**MOT #18**

2018-07-19 09:31

MOT test number

558425191750

Result

✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened heavily pitted / scored but performance requirements met (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Nearside Non obligatory mirror damaged outer casing damaged, no sharp edges**MOT #17**

2017-07-26 09:43

MOT test number

645559080611

Result

✓ Passed

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened pitted (3.5.1i)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Drag link end ball joint has slight play both n/s & o/s rack ends (2.2.B.1f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #16**

2016-07-25 09:30

MOT test number

838615359099

Result

✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front Brake hose slightly deteriorated both sides (3.6.B.4d)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)



MOT #15	2016-07-25 09:30
MOT test number	901778125680
Result	✗ Failed
Advice	Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Front Brake hose slightly deteriorated both sides (3.6.B.4d)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)

MOT #14	2015-07-29 10:10
MOT test number	510793238439
Result	✓ Passed



MOT #13 2014-09-05 10:35

MOT test number 375678944214

Result ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Nail in offside front tyre
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Play in steering rack inner joint(s)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Notice** Nearside front tyre cut side to side, not to cords
- Advice** Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Nail in nearside rear tyre
- Advice** Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Fuel filter corroded
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12**

2014-08-26 14:31

MOT test number

249008134223

Result**✗ Failed**

- Fail** Front registration plate deteriorated (6.3.1d)
- Advice** Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Play in steering rack inner joint(s)
- Fail** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front tyre cut side to side, not to cords
- Fail** Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nail in nearside rear tyre
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Notice** Fuel filter corroded
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Front Brake hose slightly deteriorated (3.6.B.4d)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Notice** Nail in offside front tyre
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #11**

2012-10-02 14:20

MOT test number

216506472209

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Rear exhaust deteriorated**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #10**

2011-08-30 15:21

MOT test number

526752041297

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Brake hose slightly chafed (3.6.B.4d)**Notice** Oil leak**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



MOT #9 2011-08-30 11:30

MOT test number 805812841234

Result ✗ Failed

Fail Rear Exhaust system not adequately supported (7.1.1)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Notice Rear brake discs pitted

Advice Nearside Front Brake hose slightly chafed (3.6.B.4d)

Pass with rectification Headlamp aim too low (1.8)

Fail Driver's door cannot be opened from inside the vehicle (6.2.B.1b)

Notice Oil leak

Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #8 2010-08-20 17:41

MOT test number 444612230266

Result ✓ Passed



MOT #7	2010-08-16 15:22
MOT test number	350828120449
Result	✗ Failed
Fail	Nearside Front front brake juddering severely (3.7.A.2b)
Notice	Slight damage to o/s/f door
Notice	Rear discs slightly worn
Fail	Offside rear brake recording little or no effort (3.7.B.5a)
Notice	Slight play n/s inner rack arm
Fail	Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Notice	Oil leak
Fail	Offside Front front brake juddering severely (3.7.A.2b)
Notice	Front number plate slight crack in it
Notice	Front discs worn advise change
Fail	Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Notice	Slight damage to n/s mirror backing
Fail	Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b)

**MOT #6**

2009-09-09 11:55

MOT test number

642082859280

Result

✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Rear brake disc slightly pitted (3.5.1h)

Notice Non obligatory mirror damaged

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Front brake disc slightly pitted (3.5.1h)

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #5

2008-07-29 16:00

MOT test number

882181818263

Result

✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4

2007-07-25 10:49

MOT test number

443286507258

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2007-07-25 10:49**MOT test number** 140766807270**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2006-08-31 16:14**MOT test number** 351663546498**Result** ✓ Passed**Notice** Power steering pipes rusting**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Front number plate discolouring**Notice** Both front tyre walls worn**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



MOT #1	2006-08-30 16:38
MOT test number	343872946255
Result	✗ Failed
Fail	Offside Rear Wheel bolt(s) missing (4.2.A.1e)
Notice	Front number plate discolouring
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
Fail	Offside Front Front position lamp(s) not working (1.1.A.3b)
Notice	Both front outer tyre walls worn
Fail	Centre Rear Exhaust system not adequately supported (7.1.1)
Notice	Power steering pipes rusting



Tax & MOT check

✕
Untaxed

Tax expired:
13 February 2021

✕
MOT

Expired:
28 July 2021

Tax status	Expired at 13 February 2021
Days left	1170 days too late
MOT expiry date	28 July 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-02-28
Last registration	2020-07-18
Complete history	See info



Registration #1	2002-02-28	24 mi
Registration #2	2006-08-30	68.529 mi
Registration #3	2006-08-31	68.593 mi
Registration #4	2007-07-25	81.820 mi
Registration #5	2008-07-29	93.046 mi
Registration #6	2009-09-09	99.478 mi
Registration #7	2010-08-16	103.238 mi
Registration #8	2010-08-20	103.274 mi
Registration #9	2011-08-30	110.724 mi
Registration #10	2011-08-30	110.730 mi
Registration #11	2012-10-02	115.534 mi
Registration #12	2013-01-01	115.534 mi
Registration #13	2013-01-01	115.534 mi
Registration #14	2013-01-01	115.534 mi
Registration #15	2013-01-01	115.534 mi
Registration #16	2013-01-01	115.534 mi
Registration #17	2013-01-01	115.534 mi
Registration #18	2013-01-01	115.534 mi
Registration #19	2013-01-01	115.534 mi
Registration #20	2013-01-01	115.534 mi
Registration #21	2013-01-01	115.534 mi
Registration #22	2013-01-01	115.534 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1803 mm
Height	1422 mm
Length	4572 mm
Wheel base	2715 mm
Kerb weight	1427 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	2762362