




General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 TDI SHUTTLE S BMT
Colour	Grey
Year of manufacture	2018
Top speed	90 mph
0 - 60 mph	21.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 83 BHP
Max. torque	220 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 2



Date	2021-12-17
Pictures	20
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-12-16
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-14
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	5
Total items failed	5

MOT #7	2024-01-15 12:22
MOT test number	605030970651
Result	✓ Passed
Next expiry date	2025-01-14

MOT #6	2024-01-12 12:21
MOT test number	922297274701
Result	✗ Failed
Fail	Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
Advice	Tyre worn close to legal limit/worn on edge BOTH FRONT TYRES LOW 255/35R20 (5.2.3 (e))

MOT #5	2023-01-13 16:50
MOT test number	734141833350
Result	✓ Passed

MOT #4	2023-01-13 14:15
MOT test number	741114309738
Result	✗ Failed
Fail	Tyre has a tear, caused by separation or partial failure of its structure BOTH REAR TYRES SPLIT 255/35/20 (5.2.3 (d) (ii))
Fail	Tyre tread depth below requirements of 1.6mm BOTH FRONT TYRES LOW 255/35R20 (5.2.3 (e))

**MOT #3** 2022-01-11 16:41**MOT test number** 334745525903**Result** ✓ Passed**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2021-06-07 11:46**MOT test number** 331006668782**Result** ✓ Passed**MOT #1** 2021-06-05 10:25**MOT test number** 578069087310**Result** ✗ Failed**Fail** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	14 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LO18KGE
Plate since	2019-03-29
Current registration	 LO18KGE
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-06-23
Last registration	2024-01-15
Complete history	See info



Registration #1	2018-06-23	11 mi
Registration #2	2021-06-05	19.350 mi
Registration #3	2021-06-07	19.377 mi
Registration #4	2022-06-07	20.377 mi
Registration #5	2023-06-07	21.377 mi
Registration #6	2023-06-07	22.377 mi
Registration #7	2023-06-07	23.377 mi
Registration #8	2023-06-07	24.377 mi
Registration #9	2023-06-07	25.377 mi
Registration #10	2024-01-15	26.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2297 mm
Height	1990 mm
Length	4904 mm
Wheel base	3 mm
Kerb weight	2137 kg
Max. allowed weight	3080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	9
Number of axles	2
Engine number	CXGA104678