





### General information

## Engine & fuel consumption

| Power                   | 68 BHP             |
|-------------------------|--------------------|
| Max. torque             | 95 Nm at 4.800 rpm |
| Engine capacity         | 998 cc             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 56.5 mpg           |
| Consumption extra urban | 74.3 mpg           |
| Consumption combined    | 67.3 mpg           |
| CO2 emission            | 97 g/km            |
| CO2 label               | А                  |







# Internet history

| Entry | 2 |
|-------|---|
|       |   |

Date Pictures 2022-09-02

21

Listing price

View report







source: cargurus.co.uk



# MOT history

| MOT expiry date    | 2024-11-29 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 5          |
| Failed MOT tests   | 0          |
| Total advice items | 5          |
| Total items failed | 0          |

| MOT #5           | 2023-11-30 10:27 |
|------------------|------------------|
| MOT test number  | 876783905975     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-11-29       |

| MOT #4   |   | 2022-11-30 11:42 |
|----------|---|------------------|
| MOT test | number  | 647855512603     |
| Result   |   | ✓ Passed         |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice   | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))   |                  |
| Advice   | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #3          | 2021-10-25 09:18 |
|-----------------|------------------|
| MOT test number | 796536417606     |
| Result          | ✓ Passed         |

| MOT #2   | 2020-11-24 09:33 |
|--|------------------|
| MOT test number                                      | 224863219551     |
| Result   | ✓ Passed         |
| Minor Windscreen wiper blade defective (3.4 (b) (i)) |                  |





| MOT #1          | 2019-12-27 16:46 |
|-----------------|------------------|
| MOT test number | 341793747937     |
| Result          | ✓ Passed         |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 November 2024 | ✓<br>MOT<br>Expires:<br>29 November 2024 |
|---|--|
| Tax status                                | Valid until 1 November                   |
| Days left                                 | 186                                      |
| MOT expiry date                           | 29 November 2024                         |
| Full MOT history                          | See MOT history                          |
| Tax calculation                           |  |
| Vahiela elass                             | 19                                       |

| Vehicle class                           | 48             |
|---|----------------|
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |





#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |       |
|----------|---------|-------|
| Date     |         |       |
| Category |         | Lamp  |
| Туре     |         |       |
| Damage 2 |         | AMPL  |
| Date     |         | · · · |
| Category | 1000000 | AMPL  |
| Туре     |         |       |

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4        |





## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******   |             |
|--|-------------|
| **********   |             |
| *******  |             |
| ******   |             |
| **********   |             |
| *******  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this CITROEN had different number plates. |             |
| Number of plates   |             |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 7          |
| First mileage registration | 2016-10-31 |
| Last registration          | 2023-11-30 |
| Complete history           | See info   |



| Registration #1 | 2016-10-31 | 18 mi      |
|-----------------|------------|------------|
| Registration #2 | 2019-12-27 | 25.626 mi  |
| Registration #3 | 2020-11-24 | 28.360 mi  |
| Registration #4 | 2021-10-25 | 29.558 mi  |
| Registration #5 |            | 11.117 mi  |
| Registration #6 |            | 11.117 esi |
| Registration #7 |            | 11.777 esi |

More info >





# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 68%             |
| Children       | 73%             |
| Pedestrian     | 53%             |
| Safety systems | 71%             |
| Overall rating | 66%             |
| Video          | see crash video |



| Dimensions & weight                                    |                               |
|--|-------------------------------|
| Width  | 1615 mm                       |
| Height   | 1460 mm                       |
| Length   | 3465 mm                       |
| Wheel base   | 2340 mm                       |
| Kerb weight  | 860 kg                        |
| Max. allowed weight                                    | 1240 kg                       |
|  |                               |
| Additional information                                 |                               |
| Additional information Fuel tank capacity              | 35 I                          |
|  | 35 l<br>Multi-Point Injection |
| Fuel tank capacity                                     |                               |
| Fuel tank capacity<br>Fuel delivery                    | Multi-Point Injection         |
| Fuel tank capacity<br>Fuel delivery<br>Number of doors | Multi-Point Injection<br>5    |