



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	VELOSTER GDI
Colour	Black
Year of manufacture	2012
Top speed	125 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	137 BHP
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-08
Pictures	37
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-09-12
<b>MOT pass rate</b>	80 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	13
<b>Total items failed</b>	4

**MOT #10** 2023-09-13 08:01**MOT test number** 258857354575**Result** ✓ Passed**Next expiry date** 2024-09-12**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2022-09-13 16:41**MOT test number** 778939969605**Result** ✓ Passed**MOT #8** 2021-07-10 11:58**MOT test number** 910319148071**Result** ✓ Passed**MOT #7** 2020-01-27 16:49**MOT test number** 864764529294**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2020-01-24 10:04**MOT test number** 792497052962**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #5** 2019-01-29 12:05**MOT test number** 403766756312**Result** ✓ Passed**MOT #4** 2019-01-25 17:11**MOT test number** 384596096282**Result** ✗ Failed**Fail** Headlamp not working on dipped beam NEARSIDE FRONT AND OFFSIDE FRONT (4.1.1 (a) (ii))**MOT #3** 2017-12-09 09:46**MOT test number** 495347930682**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Both rear and n/s/f tyres have cuts in sidewall but not to cords**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)



MOT #2	2016-12-06 13:33
MOT test number	926587218987
Result	✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Advice	Offside Rear tyre has small cut in sidewall not to cords
Advice	Nearside Rear tyre has small cut in sidewall but not to cords
Advice	Offside Rear tyre has flat spot on tread

MOT #1	2015-12-12 11:03
MOT test number	943948421699
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
12 September 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	12 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-12-14
Last registration	2023-09-13
Complete history	<a href="#">See info</a>



Registration #1	2012-12-14	12 mi
Registration #2	2015-12-12	29.649 mi
Registration #3	2016-12-06	36.287 mi
Registration #4	2017-12-09	6.184 mi
Registration #5	2019-01-25	15.733 mi
Registration #6	2019-01-29	15.756 mi
Registration #7	2019-01-29	15.777 mi
Registration #8	2019-01-29	15.777 mi
Registration #9	2019-01-29	15.777 mi
Registration #10	2019-01-29	15.777 mi
Registration #11	2019-01-29	15.777 mi
Registration #12	2019-01-29	15.777 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

**Engine number**

G4FDBU731479