



WG55XFB

report date: 2024-03-28

General information

Make	MAZDA
Model	RX-8 RX-8 192PS
Colour	Black
Year of manufacture	2005
Top speed	139 mph
0 - 60 mph	7.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	220 Nm at 5.000 rpm
Engine capacity	2.616 cc
Fuel type	Petrol
Consumption city	18.7 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.2 mpg
CO2 emission	267 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-11-14
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-11-23
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	30
Total items failed	22

MOT #19	2021-11-24 12:41
MOT test number	306482729038
Result	✓ Passed
Next expiry date	2022-11-23

MOT #18	2021-11-23 17:28
MOT test number	126016816340
Result	✗ Failed
Fail	Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))

MOT #17	2021-02-11 15:53
MOT test number	606936523693
Result	✓ Passed

**MOT #16**

2021-01-30 09:02

MOT test number

278636369426

Result**✗ Failed**

- Fail** Offside Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Service brake excessively binding all (1.2.1 (f))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Headlamp levelling device inoperative (4.1.5 (a))
- Fail** Upper Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #15

2019-05-30 15:42

MOT test number

668024093578

Result**✓ Passed**

- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Exhaust noisy (8.1.1 (a))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))



MOT #142019-05-30 15:42

MOT test number986185144093

Result		✗ Failed
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Exhaust noisy (8.1.1 (a))	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Pass with rectification	Headlamp aim too low (4.1.2 (a))	
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	

**MOT #13**

2019-04-26 08:20

MOT test number

656351429612

Result**✗ Failed**

- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Fail** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
- Fail** Undertray likely to become detached (6.2.1 (a) (ii))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Nearside Front Headlamp light source and lamp not compatible (4.1.4 (c))
- Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Front Bumper insecure (6.1.4 (a) (i))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))
- Advice** Exhaust noisy (8.1.1 (a))
- Fail** Nearside Headlamp incorrect colour (4.1.4 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))



MOT #12	2018-04-06 15:31
MOT test number	191138149658
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #11	2018-04-06 08:25
MOT test number	935147262001
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Front position lamp(s) not working (1.1.A.3b)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Headlamp not working on dipped beam (1.7.5a)

MOT #10	2017-04-19 07:47
MOT test number	382739769622
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9	2017-04-19 07:47
MOT test number	527942575246
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Headlamp aim too low Adjusted OK (1.8)

MOT #8	2016-04-18 14:03
MOT test number	956043624623
Result	✓ Passed

**MOT #7** 2015-04-02 15:04**MOT test number** 179342895411**Result** ✓ Passed**Notice** Both rear tyres worn on inner edges**MOT #6** 2014-04-10 10:28**MOT test number** 349790404149**Result** ✓ Passed**MOT #5** 2013-03-13 17:33**MOT test number** 299902473049**Result** ✓ Passed**MOT #4** 2012-03-13 12:48**MOT test number** 176943972082**Result** ✓ Passed**MOT #3** 2011-01-21 14:30**MOT test number** 998201521034**Result** ✓ Passed**MOT #2** 2009-11-05 12:35**MOT test number** 992709309385**Result** ✓ Passed**MOT #1** 2008-11-10 09:53**MOT test number** 800875018371**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
26 September 2022

✕
MOT

Expired:
23 November 2022

Tax status	Expired at 26 September
Days left	580 days too late
MOT expiry date	23 November 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-11-10
Last registration	2021-11-24
Complete history	See info



Registration #1	2005-11-10	11 mi
Registration #2	2008-11-10	32.484 mi
Registration #3	2009-11-05	40.401 mi
Registration #4	2011-01-21	49.423 mi
Registration #5	2012-03-13	53.260 mi
Registration #6	2013-03-13	57.145 mi
Registration #7	2014-04-10	59.999 mi
Registration #8	2015-04-02	64.391 mi
Registration #9	2016-04-18	65.695 mi
Registration #10	2017-04-19	66.163 mi
Registration #11	2017-04-19	66.163 mi
Registration #12	2018-05-20	66.163 mi
Registration #13	2019-05-20	66.163 mi
Registration #14	2020-05-20	66.163 mi
Registration #15	2021-05-20	66.163 mi
Registration #16	2022-05-20	66.163 mi
Registration #17	2023-05-20	66.163 mi
Registration #18	2024-05-20	66.163 mi
Registration #19	2025-05-20	66.163 mi
Registration #20	2026-05-20	66.163 mi
Registration #21	2027-05-20	66.163 mi

More info >



Dimensions & weight

Width	1771 mm
Height	1340 mm
Length	4435 mm
Wheel base	2700 mm
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	13B481900