



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B200 CDI SE
Colour	Silver
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	9.7 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	138 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-30
Pictures	27
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-12-16
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #16 2023-12-01 16:56**MOT test number** 532239802288**Result** ✓ Passed**Next expiry date** 2024-12-16**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #15** 2022-11-29 09:59**MOT test number** 718727632423**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2021-12-08 14:00**MOT test number** 371792559305**Result** ✓ Passed

**MOT #13** 2020-12-17 14:55**MOT test number** 844165745727**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Chip in screen**MOT #12** 2020-12-17 14:55**MOT test number** 857892107496**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Chip in screen**Pass with rectification** Offside Headlamp light intensity severely reduced (4.1.4 (a))**MOT #11** 2019-12-02 13:20**MOT test number** 453892690240**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2018-12-07 14:23**MOT test number** 700082368514**Result** ✓ Passed**MOT #9** 2018-12-04 16:47**MOT test number** 249773006257**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #8** 2017-11-23 09:34**MOT test number** 728034150497**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear tyre is deteriorating slightly**Advice** Offside Front tyre wearing on both edges slightly**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear tyre is deteriorating slightly**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-12-07 11:27**MOT test number** 823352202032**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-12-15 11:58**MOT test number** 564915236577**Result** ✓ Passed**MOT #5** 2014-10-15 16:00**MOT test number** 306488684285**Result** ✓ Passed

**MOT #4** 2014-10-10 14:27**MOT test number** 759733284242**Result** ✓ Passed**Notice** Nearside front tyre outer wall has a cut but not showing cord**MOT #3** 2013-11-01 11:23**MOT test number** 198555403312**Result** ✓ Passed**MOT #2** 2012-11-05 16:03**MOT test number** 426050312399**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2012-07-27 10:09**MOT test number** 165259902265**Result** ✓ Passed**Advice** Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
16 December 2024

Tax status		Valid until 1 September
Days left		126
MOT expiry date		16 December 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 KS09TUW
Plate since	2019-09-29
Current registration	 KS09TUW
Plate since	2019-09-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-07-29
Last registration	2023-12-01
Complete history	See info



Registration #1	2009-07-29	29 mi
Registration #2	2012-07-27	20.565 mi
Registration #3	2012-11-05	23.017 mi
Registration #4	2013-11-01	27.183 mi
Registration #5	2014-10-10	31.652 mi
Registration #6	2014-10-15	31.854 mi
Registration #7	2015-12-15	39.093 mi
Registration #8	2016-12-07	41.955 mi
Registration #9	2017-11-23	43.923 mi
Registration #10	2018-01-01	45.000 mi
Registration #11	2018-01-01	45.000 mi
Registration #12	2018-01-01	45.000 mi
Registration #13	2018-01-01	45.000 mi
Registration #14	2018-01-01	45.000 mi
Registration #15	2018-01-01	45.000 mi
Registration #16	2018-01-01	45.000 mi
Registration #17	2018-01-01	45.000 mi
Registration #18	2018-01-01	45.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094130632246