



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX GHIA TDCI EU4
Colour	Grey
Year of manufacture	2006
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	321 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-28
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-12-15
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	17
Total items failed	4

MOT #19	2022-12-09 11:16
MOT test number	686389580232
Result	✓ Passed
Next expiry date	2023-12-15
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18	2021-12-16 13:30
MOT test number	548967727041
Result	✓ Passed

MOT #17	2020-10-27 15:09
MOT test number	372634022399
Result	✓ Passed

MOT #16	2020-10-26 10:40
MOT test number	556604071927
Result	✗ Failed
DANGEROUS	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #15** 2019-11-05 14:11**MOT test number** 527411383358**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #14** 2018-11-12 13:01**MOT test number** 605631944950**Result** ✓ Passed**MOT #13** 2017-11-14 14:46**MOT test number** 704922096690**Result** ✓ Passed**MOT #12** 2017-11-14 13:16**MOT test number** 794515160044**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #11** 2016-11-17 11:10**MOT test number** 472503558137**Result** ✓ Passed**MOT #10** 2015-11-18 15:43**MOT test number** 832699138676**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2014-11-17 13:12**MOT test number** 788601324351**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-11-13 13:39**MOT test number** 167337613379**Result** ✓ Passed**MOT #7** 2012-11-22 19:49**MOT test number** 919747322345**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2011-09-14 16:00**MOT test number** 105417751238**Result** ✓ Passed**MOT #5** 2011-09-14 16:00**MOT test number** 379617351479**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #4** 2010-09-21 11:53**MOT test number** 561444460253**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Oil leak**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Front windscreen wipers starting to smear**MOT #3** 2010-09-20 12:54**MOT test number** 584853660256**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Oil leak**Fail** Nearside Front Road wheel bead rim badly distorted (4.2.A.1a)**Notice** Front windscreen wipers starting to smear**MOT #2** 2009-09-22 14:51**MOT test number** 764785769270**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2009-09-21 13:51**MOT test number** 360894069414**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-26
Last registration	2022-12-09
Complete history	See info



Registration #1	2006-09-26	14 mi
Registration #2	2009-09-21	27.791 mi
Registration #3	2009-09-22	27.791 mi
Registration #4	2010-09-20	34.544 mi
Registration #5	2010-09-21	34.548 mi
Registration #6	2011-09-14	39.882 mi
Registration #7	2012-11-22	46.925 mi
Registration #8	2013-11-13	52.455 mi
Registration #9	2014-11-17	58.706 mi
Registration #10	2015-11-18	64.473 mi
Registration #11	2016-09-20	65.277 mi
Registration #12	2016-09-20	65.277 mi
Registration #13	2016-09-20	65.277 mi
Registration #14	2016-09-20	65.277 mi
Registration #15	2016-09-20	65.277 mi
Registration #16	2016-09-20	65.277 mi
Registration #17	2016-09-20	65.277 mi
Registration #18	2016-09-20	65.277 mi
Registration #19	2016-09-20	65.277 mi
Registration #20	2016-09-20	65.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1544 kg
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6B76713