



report date: 2024-03-28

General information

Make	JAGUAR
Model	XKR
Colour	Black
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	4.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	510 BHP
Max. torque	625 Nm at 4.000 rpm
Engine capacity	5.000 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.9 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.0 mpg
CO2 emission	292 g/km
CO2 label	M







Internet history

Entry 1

Date	2021-09-02
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-06
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	24
Total items failed	7

MOT #17	2023-07-07 07:49
MOT test number	469221025535
Result	✓ Passed
Next expiry date	2024-07-06
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2022-07-02 10:14
MOT test number	165690147672
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-07-01 10:12
MOT test number	927298372197
Result	✗ Failed
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2021-07-15 10:28
MOT test number	141838097328
Result	✓ Passed

**MOT #13** 2020-08-06 15:30**MOT test number** 714984694431**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2020-08-06 09:23**MOT test number** 861207173399**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #11** 2019-07-30 12:35**MOT test number** 367040196138**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #10** 2018-08-08 13:51**MOT test number** 996512889737**Result** ✓ Passed**Advice** Rear sub frame corroded**Advice** Slight play in the rear suspension bushes**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Rear sub frame to body stiffener brace corroded

**MOT #9** 2017-08-31 14:55**MOT test number** 136487277748**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2016-08-23 15:04**MOT test number** 402101459813**Result** ✓ Passed**Advice** Nearside Front Upper Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Upper Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2016-08-23 13:13**MOT test number** 950212999835**Result** ✗ Failed**Advice** Nearside Front Upper Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Upper Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2015-08-27 15:33**MOT test number** 544057776391**Result** ✓ Passed**MOT #5** 2015-08-26 00:00**MOT test number** 414684578375**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)



MOT #4	2014-08-28 09:47
MOT test number	727340744233
Result	✓ Passed
Advice	Offside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Notice	Front ABS wires.

MOT #3	2014-08-28 09:47
MOT test number	125450844278
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Advice	Offside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Pass with rectification	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
Notice	Front ABS wires.

MOT #2	2013-10-01 10:47
MOT test number	105084473206
Result	✓ Passed

MOT #1	2012-09-24 14:36
MOT test number	596808662240
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
6 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	YD59FSU
Plate since	2019-03-28
Current registration	YD59FSU
Plate since	2019-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-29
Last registration	2023-07-07
Complete history	See info



Registration #1	2009-09-29	28 mi
Registration #2	2012-09-24	18.508 mi
Registration #3	2013-10-01	29.698 mi
Registration #4	2014-08-28	35.774 mi
Registration #5	2015-08-26	50.463 mi
Registration #6	2015-08-27	50.464 mi
Registration #7	2016-08-23	63.725 mi
Registration #8	2016-08-23	63.726 mi
Registration #9	2017-08-31	72.124 mi
Registration #10	2019-09-29	95.377 mi
Registration #11	2019-09-29	95.377 mi
Registration #12	2019-09-29	95.377 mi
Registration #13	2019-09-29	95.377 mi
Registration #14	2019-09-29	95.377 mi
Registration #15	2019-09-29	95.377 mi
Registration #16	2019-09-29	95.377 mi
Registration #17	2019-09-29	95.377 mi
Registration #18	2019-09-29	95.377 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4794 mm
Wheel base	2752 mm
Kerb weight	1800 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	09022801290508PS