




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI BLUEMOTION TECHNOLO
Colour	Grey
Year of manufacture	2016
Top speed	134 mph
0 - 100 km/h	8.9 seconds
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-08-27
Pictures	21
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-08-25
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	7
Total items failed	7

MOT #7	2023-07-28 15:02
MOT test number	318156875336
Result	✓ Passed
Next expiry date	2024-07-27

MOT #6	2023-07-27 10:20
MOT test number	586927301104
Result	✗ Failed
Fail	Offside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #5	2022-07-28 08:22
MOT test number	838638788861
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2022-07-26 15:38**MOT test number** 943098946493**Result** ✗ Failed**Fail** Offside Headlamp aim too high (4.1.2 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2021-06-24 08:57**MOT test number** 945905399009**Result** ✓ Passed**MOT #2** 2020-07-06 11:22**MOT test number** 237283949290**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2019-06-26 10:29**MOT test number** 782041028336**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-07-20
Last registration	2023-07-28
Complete history	See info



Registration #1	2016-07-20	8 mi
Registration #2	2019-06-26	44.007 mi
Registration #3	2020-07-06	81.662 mi
Registration #4	2021-06-24	95.733 mi
Registration #5	2022-06-24	110.000 mi
Registration #6	2023-06-24	125.000 mi
Registration #7	2023-06-24	140.000 mi
Registration #8	2023-06-24	155.000 mi
Registration #9	2023-06-24	170.000 mi
Registration #10	2023-06-24	185.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	2083 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1441 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	CRLB379607