





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	VIANO 116 CDI TRAVELINER
Colour	Silver
Year of manufacture	2013
Top speed	113 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 kW / 163 HP / 163 BHP
Max. torque	360 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	214 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2022-11-15

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-11

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-01-08
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	6
Total items failed	9

MOT #14	2024-01-09 13:45
MOT test number	488125564740
Result	✓ Passed
Next expiry date	2025-01-08
Advice Front Tyre worn close to legal limit/worn on edge Both. (5.2.3 (e))	

MOT #13	2022-06-24 10:52
MOT test number	822408567664
Result	✓ Passed
MOT #12	2021-06-17 15:50
MOT test number	952829722073
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #11 2021-04-26 09:42

MOT test number 421951615587

Result X Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Central Seat belt buckle damaged (7.1.2 (d))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Windscreen in an unacceptable condition excessive damage over 40mm in n/s swept area (3.2 (c) (i))

MOT #10 2020-04-25 14:22

MOT test number 571035651430

MOT #9 2019-02-27 14:15

MOT test number 324437732559

Result ✓ Passed

MOT #8 2018-08-31 16:27

MOT test number 866894624304

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #7 2018-02-27 16:35

MOT test number 185017568878

Advice Engine under trays fitted obscuring some underside components.

CarCheck.co.uk page 4/13



MOT #6 2018-02-26 14:40 **MOT test number** 608138641977 Result × Failed Fail Offside Rear Registration plate lamp not working (1.1.C.1d) Offside Front Headlamp aim too low (1.8) Fail Fail Rear Direction indicators incorrect colour (1.4.A.2f) Advice Engine under trays fitted obscuring some underside components. Nearside Front Headlamp aim too low (1.8) Fail Fail Offside Direction indicator not working side repeater in mirror housing (1.4.A.2c)

MOT #5	2017-08-30 16:50
MOT test number	561541229636
Result	✓ Passed
MOT #4	2017-02-28 13:48
MOT test number	193802982176
Result	✓ Passed
Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)	

Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)	
MOT #3	2016-08-31 14:11
MOT test number	187015573368
Result	✓ Passed
MOT #2	2016-03-04 11:16
MOT test number	699392573881
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2015-09-04 11:35

MOT test number 273396422002

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK ZIP
Plate since	
Current registration	NK SIE
Plate since	

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-03-27
Last registration	2024-01-09
Complete history	See info



Registration #1	2013-03-27	10 mi
Registration #2	2015-09-04	46.860 mi
Registration #3	2016-03-04	50.750 mi
Registration #4	2016-08-31	56.389 mi
Registration #5	2017-02-28	62.684 mi
Registration #6	2017-08-30	69.508 mi
Registration #7	2018-02-26	80.333 mi
Registration #8	2018-02-27	80.339 mi
Registration #9	2018-08-31	90.716 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		0.00 44
Registration #17		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2253 mm
Height	1875 mm
Length	5008 mm
Wheel base	3430 mm
Kerb weight	2085 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of doors	5
CarChaeleeaule	nowo 12/12

CarCheck.co.uk page 13/13

Number of seats	9
Number of axles	2
Engine number	65194031095051