





General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 308 S/S ALLURE |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 117 mph |
| 0 - 60 mph | 11.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 110 BHP |
|-------------------------|---------------------|
| Max. torque | 205 Nm at 1.500 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 107 g/km |
| CO2 label | В |







Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-06-21 |
| Pictures | 20 |
| Listing price | View report |









source: yesauto.com



MOT history

| MOT expiry date | 2024-05-20 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 20 |
| Total items failed | 4 |

| MOT #6 | | 2023-05-16 08:29 |
|--------------------------|--|-----------------------------|
| MOT test nu | mber | 119658674513 |
| Result | | ✓ Passed |
| Next expiry | date | 2024-05-20 |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice C Rear bush (5 | Offside Front Lower Suspension arm pin or bush worn but not resulti .3.4 (a) (i)) | ng in excessive movement |
| Advice | learside Front Tyre worn close to legal limit/worn on edge on 2mm 2 | 225-45-17 (5.2.3 (e)) |
| Advice | learside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | learside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice N Rear bush (5 | learside Front Lower Suspension arm pin or bush worn but not resul .3.4 (a) (i)) | Iting in excessive movement |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge 225-4 | 45-17 (5.2.3 (e)) |
| Advice | Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) | |



MW67SXU report date: 2024-03-29

| MOT #5 2023-05-15 | 5 08:42 |
|--|---------|
| MOT test number 4293769 | 974281 |
| Result | Failed |
| Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge on 2mm 225-45-17 (5.2.3 (e)) | |
| Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movem Rear bush (5.3.4 (a) (i)) | nent |
| Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Fail Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice Offside Front Inner Tyre worn close to legal limit/worn on edge 225-45-17 (5.2.3 (e)) | |
| Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movemer Rear bush (5.3.4 (a) (i)) | nt |

| МОТ #4 | 2022-05-18 15:33 |
|-----------------|------------------|
| MOT test number | 664493055433 |
| Result | ✓ Passed |

| MOT #3 | 2022-05-18 09:33 |
|---|--------------------------|
| MOT test number | 939037695555 |
| Result | 🗙 Failed |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or (i)) | light sources (4.7.1 (b) |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |



| Μ | W67SXU |
|---|-------------------------|
| | report date: 2024-03-29 |

| MOT #2 | 2021-05-21 16:11 |
|--|--------------------------------|
| MOT test number | 911254479905 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2020-12-21 11:39 |
| MOT test number | 717062996902 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge low t | tread 3.1mm approx (5.2.3 (e)) |



MW67SXU report date: 2024-03-29

Tax & MOT check

| √ Taxed | мот |
|----------------------------|-------------------------|
| Tax due: 1 January 2025 | Expires: 20 May 2024 |
| Tax status | Valid until 1 January |
| Days left | 246 |
| MOT expiry date | 20 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2018-01-08 |
| Last registration | 2023-05-16 |
| Complete history | See info |



| Registration #1 | 2018-01-08 | 21 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-12-21 | 18.317 mi |
| Registration #3 | 2021-05-21 | 19.648 mi |
| Registration #4 | | 11.117 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.117 mi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 79% |
| Pedestrian | 64% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1804 mm |
| Height | 1457 mm |
| Length | 4253 mm |
| Wheel base | 2620 mm |
| Kerb weight | 1080 kg |
| Max. allowed weight | 1720 kg |
| Additional information | |
| Fuel tank capacity | 53 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | XVA20940338 |