





report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK 55 AMG
Colour	Silver
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	5.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	367 BHP
Max. torque	510 Nm at 4.000 rpm
Engine capacity	5.439 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.6 mpg
Consumption extra urban	32.5 mpg
Consumption combined	23.3 mpg
CO2 emission	290 g/km
CO2 label	М



CarCheck.co.uk page 1/13



Internet history

Entry 1


Date 2021-06-30

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-19
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	20
Total items failed	11

MOT #17	2023-10-20 14:19
MOT test number	249304994655
Result	✓ Passed
Next expiry date	2024-10-19
Advice Offside Rear Brake pipe corroded, covered in grease or other material c underseal (1.1.11 (c))	overed in stone chip
Advice Nearside Rear Brake pipe corroded, covered in grease or other material covered in stone chip underseal (1.1.11 (c))	
Advice Central Front undertrays missing	

MOT #16	2021-02-02 17:31
MOT test number	592650867967
Result	✓ Passed
MOT #15	2019-12-10 12:23
MOT test number	698976430008
Result	✓ Passed
Advice Coolant level warning on	

CarCheck.co.uk page 3/13



MOT #14

LRO3KXL report date: 2024-03-29

2019-12-10 12:23

MOT test number 714026841755

Result X Failed

Pass with rectification Front Registration plate missing (0.1 (a))

Advice Coolant level warning on

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

MOT #13 2016-12-12 10:27

MOT test number 204656851926

Result
✓ Passed

MOT #12 2014-02-22 12:57

MOT test number 835953554034

Result \(\sqrt{Passed} \)

Advice Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

MOT #11 2014-02-22 12:57

MOT test number 856023954037

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Headlamp aim too high and too far to the right. (1.8)

Pass with rectification Nearside Headlamp aim too high and too far to the right. (1.8)

Advice Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

MOT #10 2013-01-22 14:33

MOT test number 929642423030

CarCheck.co.uk page 4/13



Fail

LRO3KXL report date: 2024-03-29

MOT #9 2012-11-24 12:52

MOT test number 456359322391

Result X Failed

Notice Headlamp washers do not operate

Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #8 2011-11-23 10:42

MOT test number 508397021351

Result \rightarrow Passed

Advice Nearside Outer Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Nearside rear tyre cut inner wall. Replacement needed.

MOT #7 2010-10-07 11:54

MOT test number 441230880282

Result X Failed

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

Advice Centre Rear Stop lamp deteriorated, but still visible from a reasonable distance (1.2.1d)

MOT #6 2010-10-07 11:54

MOT test number 632570780235

Result J Passed

Advice Centre Rear Stop lamp deteriorated, but still visible from a reasonable distance (1.2.1d)

CarCheck.co.uk page 5/13



MOT #5

Result

Fail

LR03KXL report date: 2024-03-29

2009-10-01 15:47

X Failed

640354779265 **MOT** test number

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2009-09-29 14:49

MOT test number 992792279253

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Front brake disc excessively scored (3.5.1h)

MOT #3 2008-09-27 14:45

MOT test number 663781378230

Result ✓ Passed

Front Brake pad(s) wearing thin (3.5.1g) **Advice**

Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2007-07-17 16:29

MOT test number 681088397185

Result ✓ Passed

MOT #1 2006-04-01 09:46

MOT test number 412551096094

✓ Passed Result

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
venicle class	70
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK
Plate since	
Current registration	AIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2003-03-31
Last registration	2023-10-20
Complete history	See info



Registration #1	2003-03-31	20 mi
Registration #2	2006-04-01	30.399 mi
Registration #3	2007-07-17	44.580 mi
Registration #4	2008-09-27	48.734 mi
Registration #5	2009-09-29	55.127 mi
Registration #6	2009-10-01	55.128 mi
Registration #7	2010-10-07	61.781 mi
Registration #8	2011-11-23	67.565 mi
Registration #9	2012-11-24	83.968 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		
Registration #15		11.777 es
Registration #15 Registration #16		11.77 m

More info >

CarCheck.co.uk page 12/13



<u> </u>		_		
luma	ensior	וכ אי	MAIO	Int
		is a	WCIU	ш

Width	1740 mm
Height	1413 mm
Length	4638 mm
Wheel base	2715 mm
Kerb weight	1715 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	11398760043019

CarCheck.co.uk page 13/13