





report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 SPORTIUM
Colour	White
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/13




Internet history

Entry 1

Date 2021-07-05

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-07
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	25
Total items failed	12

MOT #15	2023-10-16 12:20
MOT test number	309873378237
Result	✓ Passed
Next expiry date	2024-11-07

MOT #14	2023-10-11 09:35
MOT test number	388729289503
Result	X Failed
Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #13	2022-11-08 16:34
MOT test number	123223294781
Result	✓ Passed
MOT #12	2022-01-06 12:18
MOT test number	881445840862
Result	✓ Passed
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



MOT #11 2022-01-06 12:18

MOT test number 133036346751

Result X Failed

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Pass with rectification Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

MOT #10 2020-12-11 16:46

MOT test number 874668582680

Result
✓ Passed

Advice Oil leak, but not excessive sump corroded. (8.4.1 (a) (i))

MOT #9 2020-12-07 11:34

MOT test number 718216565144

Result × Failed

Advice Oil leak, but not excessive sump corroded. (8.4.1 (a) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Upper Macpherson strut mounting damaged and seriously weakened top mounting. (5.3.3 (b) (i))

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure perished. (5.2.3 (d) (ii))

MOT #8 2019-04-11 09:29

MOT test number 264228243502

CarCheck.co.uk page 4/13



MOT test number

Result

Advice Nearside Front Outer Drive shaft boot clip is broken

Exhaust bracket broken off at downpipe

2018-04-17 09:11

242372962782

✓ Passed

Advice Exhaust bracket broken off at downpipe

MOT test number

Result

Advice Nearside Front Outer Drive shaft boot clip is broken

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Advice Exhaust bracket broken off at downpipe

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

MOT #5

MOT test number

783902099687

Result

✓ Passed

MOT #4 2016-05-13 15:02 **MOT** test number 653031357379 Result ✓ Passed **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Under trays fitted covering underside components. Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) Oil leak from engine. **Advice** Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 5/13



MOT #3 2016-05-13 14:21

MOT test number 687406179422

Result X Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Under trays fitted covering underside components.

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Oil leak from engine.

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2015-05-27 08:59

MOT test number 536347345189

Result \(\sqrt{Passed} \)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2015-05-26 11:19

MOT test number 817696445145

Result × Failed

Fail Exhaust system not adequately supported (7.1.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	history
OWITCE	iliotoi y

,		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		IGEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-05-29
Last registration	2023-10-16
Complete history	See info



Registration #1	2012-05-29	24 mi
Registration #2	2015-05-26	13.510 mi
Registration #3	2015-05-27	13.510 mi
Registration #4	2016-05-13	17.052 mi
Registration #5	2016-05-13	17.052 mi
Registration #6	2017-05-04	19.632 mi
Registration #7	2018-04-17	30.291 mi
Registration #8	2018-04-17	30.291 mi
Registration #9	2019-04-11	44.796 mi
9		
Registration #10		11.777 es
		11.777 es
Registration #10		11.777 es 11.777 es 11.777 es
Registration #10 Registration #11		11.777-00 11.777-00 11.777-00 11.777-00
Registration #10 Registration #11 Registration #12		11.777-00 11.777-00 11.777-00 11.777-00
Registration #10 Registration #11 Registration #12 Registration #13		10 777 es
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		10 777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number FSX46410607