





General information

Make	MAZDA
Model	3 D SPORT NAV
Colour	Blue
Year of manufacture	2016
Top speed	116 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.496 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	А





Internet history

E	n	tı	ry	1

Date Pictures 2021-05-24

20

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-15
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	15
Total items failed	2

MOT #6	2023-07-11 11:33
MOT test number	101204463342
Result	Passed
Next expiry date	2024-07-15
Minor Nearside Registration plate lamp inoperative in the case of multiple la (b) (i))	mps or light sources (4.7.1

MOT #5	2022-07-08 13:49
MOT test number	657793303014
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge tread at 2m	m (5.2.3 (e))

MOT #4	2021-07-16 15:43
MOT test number	656722822833
Result	✓ Passed





MOT #3	2020-08-24 15:57	
MOT test number	809200560763	
Result	✓ Passed	
Advice Nearside Front Tyre has a	a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge worn to 2.5mm and cuts in tread but not deep enough to reach cord (5.2.3 (e))		
Advice Nearside Rear Child Seat	fitted not allowing full inspection of adult belt	
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		

MOT #2	2020-08-21 14:49
MOT test number	885970788101
Result	🗙 Failed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	t
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or o	cords (5.2.3 (d) (i))
Advice Offside Rear Tyre worn close to legal limit/worn on edge worn to 2.5mr deep enough to reach cord (5.2.3 (e))	m and cuts in tread but not
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or	cords (5.2.3 (d) (i))
Fail Front Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Fail Offside Front Tyre has ply or cords exposed cut in tread exposing cord (5.2)	2.3 (d) (ii))
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously wea	akened (1.1.14 (a) (ii))

MOT #1	2019-08-30 08:58
MOT test number	559573167363
Result	✓ Passed
Advice Front Brake pads getting	low
Advice Nearside Rear Child Seat	fitted not allowing full inspection of adult belt
Advice Front Wiper blades deterio	prated



VU66MDV report date: 2024-03-28

Tax & MOT check

Tax due: 1 July 2024	✓ Taxed	Expires: 15 July 2024	√ мот
Tax status			Valid until 1 July
Days left			64
MOT expiry date			15 July 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		40	

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E Stand
Date	*
Category	AMP
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-09-01
Last registration	2023-07-11
Complete history	See info



Registration #1	2016-09-01	25 mi
Registration #2	2019-08-30	34.832 mi
Registration #3	2020-08-21	41.582 mi
Registration #4	2020-08-24	41.613 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		10.200 est

More info \rightarrow





Safety ratings

NCAP rating	****
Adult	93%
Children	86%
Pedestrian	65%
Safety systems	81%
Overall rating	85%
Video	see crash video



Dimensions & weight	
Width	1795 mm
Height	1450 mm
Length	4585 mm
Wheel base	2700 mm
Kerb weight	1340 kg
Max. allowed weight	1870 kg
Additional information	
Additional information Fuel tank capacity	51 l
	51 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4