





report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 ENTERPRISE P/V HDI
Colour	White
Year of manufacture	2016
Top speed	90 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

En	trv	2
EII	ILI V	_

Date	2021-12-14
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

y -		
Date	2021-12-13	
Pictures	12	
Listing price	View report	









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-25
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	7
Total items failed	5

MOT #8		2024-01-25 10:41
MOT test	number	564140354453
Result		✓ Passed
Next expi	y date	2025-01-25
Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))		
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or	cords (5.2.3 (d) (i))

MOT #7		2024-01-25 10:41
MOT test number		585166045705
Result		X Failed
Pass with rectificat	ion Nearside Headlamp aim too low (4.1.2 (a))	
Advice Nearside Re	ear Tyre has a cut but not deep enough to reach the ply	or cords (5.2.3 (d) (i))
Advice Front Brake	e disc worn, pitted or scored, but not seriously weakened	l Both (1.1.14 (a) (ii))
Pass with rectificat	Offside Headlamp aim too low (4.1.2 (a))	

MOT #6	2023-01-25 14:17
MOT test number	160586799614
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5

MOT test number

435595362130

Result

Pass with rectification

Offside Headlamp aim too high (4.1.2 (a))

MOT test number

Result

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #3

MOT test number

845151298180

Result

✓ Passed

MOT test number

Result

Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail

Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

 MOT #1
 2019-05-23 13:54

 MOT test number
 761802696241

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



SA16UCE report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



SA16UCE report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



SA16UCE report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

,		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



SA16UCE report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.6.	

Contact info

More info >

CarCheck.co.uk page 9/11



SA16UCE report date: 2024-03-29

Mileage check

Odometer	In kilometers
Mileage registrations	11
First mileage registration	2016-03-31
Last registration	2024-01-25
Complete history	See info



Registration #1	2016-03-31	23 mi
Registration #2	2019-05-23	19.934 mi
Registration #3	2021-01-25	46.476 mi
Registration #4	2021-01-26	46.480 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 66
Registration #11		0.777 es

More info >

CarCheck.co.uk page 10/11



SA16UCE report date: 2024-03-29

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBDF0089439

CarCheck.co.uk page 11/11