



report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMERA SE
Colour	Green
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	192 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	39.8 mpg
Consumption combined	31.7 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-06-16
Pictures	5
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-06-09
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #17 2020-07-01 12:11

MOT test number 515574853247

Result ✓ Passed

Next expiry date 2021-06-30

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front wishbone corroded
- Advice** Front lower subframe corroded
- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Underbody corrosion all over
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear chassis corroded all over
- Advice** Front and rear brake ferruls corroded
- Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))



MOT #16

2020-06-29 09:22

MOT test number

277612527111

Result

✗ Failed

DANGEROUS Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Coil spring corroded both (5.3.1 (b) (i))

Advice Front lower subframe corroded

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MAJOR Tailgate cannot be secured in the closed position (6.2.1 (e))

Advice Rear chassis corroded all over

DANGEROUS Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front and rear brake ferruls corroded

DANGEROUS Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front wishbone corroded

Advice Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Underbody corrosion all over

**MOT #15**

2019-08-19 12:38

MOT test number

441335819367

Result

✓ Passed

- Advice** Front cross member corroded
- Advice** Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Slight corrosion under body
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

MOT #14

2019-08-09 10:07

MOT test number

792664412575

Result

✗ Failed

- Advice** Front cross member corroded
- MAJOR** Brake pipe excessively corroded 2 from front to rear (1.1.11 (c))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))
- MAJOR** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Advice** Slight corrosion under body
- Advice** Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13** 2018-08-13 09:59**MOT test number** 118220525875**Result** ✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** All brake ferrules corroded
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #12 2017-07-31 13:38**MOT test number** 948712748592**Result** ✓ Passed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Anti-roll bar has slight play in a ball joint offside front (2.4.G.2)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #11 2016-08-03 09:54**MOT test number** 483783781737**Result** ✓ Passed

**MOT #10** 2015-08-19 09:54**MOT test number** 958846702872**Result** ✓ Passed**Advice** Suspension component mounting prescribed area is corroded but not considered excessive Both Rear (2.4.A.3)**Advice** Front cross member corroded**Advice** Brake hose has slight corrosion to ferrules Both front & Rear (3.6.B.4e)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2014-07-28 14:48**MOT test number** 398359104219**Result** ✓ Passed**Notice** Front cross member corroded**MOT #8** 2013-08-14 12:04**MOT test number** 526546823267**Result** ✓ Passed**MOT #7** 2012-07-30 10:10**MOT test number** 518182212228**Result** ✓ Passed**MOT #6** 2011-08-12 11:06**MOT test number** 288024121246**Result** ✓ Passed**MOT #5** 2010-08-04 10:04**MOT test number** 341056210455**Result** ✓ Passed



MOT #4	2009-08-12 10:00
MOT test number	112754229203
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #3	2008-08-05 13:09
MOT test number	153048718241
Result	✓ Passed
MOT #2	2007-08-14 15:58
MOT test number	530366727263
Result	✓ Passed
MOT #1	2006-08-23 11:58
MOT test number	664835636250
Result	✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-09-29
Last registration	2020-07-01
Complete history	See info



Registration #1	2003-09-29	13 mi
Registration #2	2006-08-23	20.037 mi
Registration #3	2007-08-14	22.318 mi
Registration #4	2008-08-05	24.839 mi
Registration #5	2009-08-12	26.822 mi
Registration #6	2010-08-04	29.020 mi
Registration #7	2011-08-12	31.150 mi
Registration #8	2012-07-30	33.018 mi
Registration #9	2013-08-14	35.114 mi
Registration #10	2014-07-28	36.603 mi
Registration #11	2015-08-01	38.114 mi
Registration #12	2016-08-01	39.603 mi
Registration #13	2017-08-01	41.114 mi
Registration #14	2018-08-01	42.603 mi
Registration #15	2019-08-01	44.114 mi
Registration #16	2020-07-01	45.603 mi
Registration #17	2021-07-01	47.114 mi
Registration #18	2022-07-01	48.603 mi
Registration #19	2023-07-01	50.114 mi
Registration #20	2024-07-01	51.603 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1482 mm
Length	4675 mm
Wheel base	2680 mm
Kerb weight	1270 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	199068